



PT. TD Automotive Compressor Indonesia

NPWP: 31.275.009.4-431.000

Office / Factory:

Jl. Selayar IV Blok L3, Kawasan Industri MM 2100  
Cikarang Barat, Bekasi 17530, Jawa Barat, Indonesia  
Phone : (+62)21 28517699 Fax : (+62)21 28517599

PURCHASE ORDER

TO : TOSEI INDONESIA,PT  
PIC : Bp.Andrianto

VAT

NO : 50020340  
DATE : 13/02/2020

NO.	ITEM DESCRIPTION	QTY	U/M	PRICE	TOTAL AMOUNT
1	INSPECTION & REPAIR COST E-TS-1096B S/N. 515182	1	SET	Rp 2,410,000	Rp 2,410,000
2	INSPECTION & REPAIR COST MODEL E-TS-1096B P3 S/N/ 520084	1	SET	Rp 2,410,000	Rp 2,410,000
3	INSPECTION & REPAIR COST MODEL E-TS-1096B S/N. 516048	1	SET	Rp 2,410,000	Rp 2,410,000
4	INSPECTION & REPAIR COST MODEL E-TS-1096B S/N. 518939	1	SET	Rp 2,410,000	Rp 2,410,000
5	SPAREPART REPAIR E-TS-1096B S/N. 516048 (MESIN OP 20E)	1	SET	Rp 5,230,020	Rp 5,230,020
6	SPAREPART REPAIR MODEL E-TS-1096B S/N. 515182 (MESIN OP 20F)	1	SET	Rp 5,230,020	Rp 5,230,020
7	SPAREPART REPAIR MODEL E-TS-1096B S/N. 518939	1	SET	Rp 7,208,480	Rp 7,208,480
8	SPAREPART REPAIR MODEL E-TS-1096B-S/N. 520084 (MESIN OP 20D)	1	SET	Rp 5,230,020	Rp 5,230,020
				TOTAL	Rp 32,538,540
NOTE: DELIVERY DUE DATE MAX : 09/03/2020 DELIVERY TO : PT. TD Aotomotive Compressor Indonesia		REMARKS:			PROCUREMENT Approved Feb 18 2020 12:35PM MASAYA NAKAMURA

This Purchase Order created by PT. TD Automotive Compressor Indonesia System (Validation by Purchasing Section without Signature)

No. : PTY-001-FT-Y004
Revision : 4