Inspection report.

Date of Report:	07-04-2026	Report Number:	20260401-011
P.O. Number:	TBA	Order Number:	20260401-01
Client:	DECO Subsea services,	Location:	Peraltastraat 5, Brugge, Belgium.
Contractor:	Rigging Service Netherlands B.V.	Location:	Stationsplein 6, 3224 AT Hellevoetsluis.
Service work completed by: RSN Offshore		Date tested:	01-04-2026
Inspection Details:		Inspected	
Container ID:	MSOU 109005-0	General conditon	Goog / Used
Manufacturer	YANGZHOU	Cornerblocks	Good / Used
Year of manufacture	2025	Padeyes	Good – Used
Manufacture serial:	Z4841	Door	Good / Used
Max gross	10mTON	Weldings overal	Good-No cracks Visible
Tare	2.2mTon	NDT	N/A
Inspected item:			
			
Inspection details:			
Method of inspection:		Visual	
Inspection and document in accordance to		DNV Regulations 2.7.1.	
Approved			
Load tested by:  Marvin Haesebrouck (RSN Offshore)		Name of the person authenticating report: N/A	