

* before the stair calibration: one of three runs did not complete (a permanent counterflow gridlock on a corner gangway); the mean of the other two