

Car Damage Insurance Claim Report

Report ID: ed125cb2-008f-4c84-a9da-282763951ac5

Date: 26-Sep-2025

Insurance Company: ABC Insurance Co.

Vehicle Owner: Deepika Saladi

Vehicle Information:

Make & Model: MARUTI SUZUKI Swift

Year: 2020

Registration Number: MH12AB1234

VIN: VIN123456789

Detected Damages:

Type	Location	Severity	Cost (\$)	Time (hrs)
Bonnet	Area 1	Minor	229	7
Light	Area 2	Moderate	340	8
Bonnet	Area 3	Minor	156	6
Bumper	Area 4	Minor	490	1
Fender	Area 5	Severe	206	7

Total Cost: \$1421

Total Repair Time: 29 hrs

Notes: This report is generated automatically based on detected damages. Actual cost/time may vary depending on parts availability.