

# Car Damage Insurance Claim Report

Report ID: cacec553-17e4-4d4e-8ec1-20c64db0b657

Date: 26-Sep-2025

Insurance Company: ABC Insurance Co.

Vehicle Owner: Deepika Saladi

Vehicle Information:

Make & Model: MARUTI SUZUKI Swift

Year: 2020

Registration Number: MH12AB1234

VIN: VIN123456789

Detected Damages:

Type	Location	Severity	Cost (\$)	Time (hrs)
Bonnet	Area 1	Minor	211	3
Light	Area 2	Moderate	259	6
Bonnet	Area 3	Minor	109	1
Bumper	Area 4	Severe	244	6
Fender	Area 5	Moderate	83	1

Total Cost: \$906

Total Repair Time: 17 hrs

Notes: This report is generated automatically based on detected damages. Actual cost/time may vary depending on parts availability.