
Figure 14 — N-1 Contingency Impact and Recovery (8-Bus)
Immediate Impact
After Recovery
Relative Performance (base_of / observed_of)
1.0
0.8
0.6
0.4
0.2
0.0
L0
L1
L2
L3
L4
L5
L6
L7
L8
Line Outage