

# STATE OF CALIFORNIA - TRAFFIC COLLISION REPORT (CHP 555)

Report Number: LA-2026-31882 Investigating Agency: Los Angeles Police Department, Central Traffic Division

Date of Collision: 02/11/2026 Time: 0814 hours NCIC: 1942

Location: Wilshire Blvd at Vermont Ave, Los Angeles, CA 90010

## PARTIES

Party 1 (P-1) DRIVER: Daniel Cho. Vehicle V-1: 2023 Subaru Outback, plate 8WJK221. Direction of travel: Northbound on Vermont Ave. Owner: Daniel Cho.

Party 2 (P-2) DRIVER: Robert Hale. Vehicle V-2: 2019 RAM 1500, plate 5TRN908. Direction of travel: Eastbound on Wilshire Blvd. Owner: Robert Hale.

## PRIMARY COLLISION FACTOR

VC Section Violated: 21453(a) - Party 2. Type of Collision: Broadside. Movement Preceding Collision (P-2): Proceeding Straight. Movement Preceding Collision (P-1): Proceeding Straight.

## STATEMENTS

P-1 (Cho) stated: 'I had a green light going north on Vermont. As I entered the intersection the pickup came through from my left and hit my driver door. I never had time to brake.'

P-2 (Hale) stated: 'I thought the light was yellow. I might have entered late.'

Independent witness W-1 (Sandra Pierce), pedestrian at the northwest corner, stated: 'The Subaru clearly had the green light. The truck ran the red - it didn't even slow down.'

## AREA OF IMPACT

AOI was determined by physical evidence (gouge marks and debris field) to be within the number 2 northbound lane, approximately 18 feet north of the south crosswalk line.

## OPINIONS AND CONCLUSIONS

Based on the physical evidence, the independent witness statement, and the signal timing data obtained from LADOT, it is my opinion that Party 2 (Hale) entered the intersection against a steady red signal in violation of CVC 21453(a) and was the sole proximate cause of this collision. Party 1 was traveling within the posted 35 mph limit and had the right of way. Reporting Officer: M. Delgado, Serial 30418.