

Signature of Customer/Collection Date

This is system generated receipt, no signature is required.

For Customer

SAMSUNG**Acknowledgement of Service Request**

Service Centre: 0002467600 - - City Aircool

Address: B-18, Saini Villa, Lohia Nagar

Ghaziabad201001

Contact Centre: 180040SAMSUNG

(1800-40-7267864)

Track Your Repair Status online: www.samsung.com/in/support

4370853242

Bill No : 4370853242 Call For Status : 91-9654320786 Delivery Time : 11 a.m. to 6 p.m. CSR Print Date : 21.05.2023 Time : 12:14:05

Customer Name	Kamal Kishore	Request Date	05.19.2023 18:59:03
Address	201012 Kamal,Kishore,sector 10 c block house 76,Vasundhara GhaziabGHAZIABAD UTTAR PRADESH09-Uttar Pradesh IN		
Appointment Date	05.19.2023 (21:02:14)	Engineer	Mohd Danish
Telephone	[Home]9717390401[Mobile]9717390401	Fax No.	
Model Name	AR18CYNZABENNA	Purchase Date	05.16.2023
Serial No. (CRT/ESN/IMEI)	05FWPPCW302824T ()	Service Type	Initial Installation
Warranty Status	Full Warranty <input type="checkbox"/> Labor Only <input type="checkbox"/> Parts Only <input type="checkbox"/> Out of Warranty <input checked="" type="checkbox"/>		
Repair Received	COPPER PIPE MISSING & FILER NUT MISSING	Repair Completed	05.20.2023
Goods Delivered	COPPER PIPE MISSING & FILER NUT MISSING	Return by / Date	
Defect Description	INSTALLATION DONE	B2B SVC	N
Accessory			
Remark	"Visit By Eng MOhd Asif 20/05 03~04.00"		
Repair Description	INSTALLATION DONE		
Condition Code	2	Symptom Code	HX8
		Defect Code	M
		Repair Code	E01

No	Parts No	Description	Location	Qty	Unit Price (INR)	Amount (INR)	Part Return Date

Total Parts Cost	INR	0.00
Labor	INR	0.00
Transportation	INR	0.00
Other amount	INR	0.00
Tax	INR	0.00
Grand Total	INR	0.00