

**ADVANCED APPRAISAL SERVICE -
MARLBORO,MA**

2 MOUNT ROYAL AVE
MARLBOROUGH, MA 01752
Phone: (508) 485-2212, FAX:(508) 485-8691

Workfile ID: 50882c7b

For:

COMMERCE INSURANCE

MAPFRE | Insurance Claims Questions Call

Phone: (800) 221-1605

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

Written By: Francisco Enriquez, 15860
Adjuster: EWINGS, CHRISTOPHER, (800) 221-1605 Business

Insured:	PEREZ, EDGAR	Policy #:	GZJ538	Claim #:	AOPY2PC-PAYXX9
Type of Loss:	AC - unknown	Date of Loss:	1/30/2019 1:00 PM	Days to Repair:	0
Point of Impact:	06 Rear				

Owner:	Inspection Location:	Repair Facility:
PEREZ, EDGAR	290 AUTO BODY / CUSTOMS	290 AUTO BODY / CUSTOMS
55 ANNA STREET	1 STOWELL AVE	1 STOWELL AVE
WORCESTER, MA 01604	WORCESTER, MA 01606	WORCESTER, MA 01606
(774) 242-8388 Business	Repair Facility	(508) 340-4977 Fax

VEHICLE

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

VIN:	1GYS4UKJ2FR708811	Production Date:		Interior Color:	
License:	9HM429	Odometer:	56,121	Exterior Color:	WHITE
State:	MA	Condition:			

TRANSMISSION

Automatic Transmission
Overdrive
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
Memory Package
Power Adjustable Pedals

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Rear Window Wiper

Telescopic Wheel

Climate Control

Dual Air Condition

Navigation System

Backup Camera w/Parking Sensors

Stereo

Search/Seek

Auxiliary Audio Connection

Premium Radio

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Rear Side Impact Air Bags

ROOF

Luggage/Roof Rack

Electric Glass Sunroof

SEATS

Bucket Seats

Leather Seats

Heated Seats

Rear Heated Seats

Ventilated Seats

Power Third Seat

WHEELS

20" Or Larger Wheels

PAINT

Three Stage Paint

OTHER

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

DECOR

Dual Mirrors

Body Side Moldings

Privacy Glass

Console/Storage

Wood Interior Trim

CONVENIENCE

Dual Screen Entertainment

Remote Starter

Intelligent Cruise

Home Link

RADIO

AM Radio

FM Radio

Communications System

Hands Free Device

Xenon Headlamps

Positraction

Blind Spot Detection

Heads Up Display

Lane Departure Warning

Signal Integrated Mirrors

TRUCK

Trailer Hitch

Trailer Package

Running Boards/Side Steps

Power Trunk/Gate Release

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADi Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	"REPAIRER, READ ESTIMATE NOTES"		1			
		Note: BEFORE starting repairs or ordering parts, please complete a 2 hour hidden damage access tear down to CONFIRM REPAIRABLE STATUS. If additional damage is discovered, CONTACT THE APPRAISER IMMEDIATELY"					
2	#	=====		1			
3	FRONT SUSPENSION						
4	Repl	Wheel alignment align front wheels		1	m	1.5	
5	Repl	Wheel alignment check rear alignment		1	m	0.5	
6	ROOF						
7	S01 R&I	R&I headliner				3.5	
8	S01	O/H luggage rack				4.0	
9	S01 R&I	RT Side rail Escalade ESV				Incl.	
10	S01	Deduct for Overlap				-0.1	
11	S01 R&I	LT Side rail Escalade ESV				Incl.	
12	S01	Deduct for Overlap				-0.1	
13	S01 R&I	Rear headliner shale				1.7	
14	S01	Deduct for Overlap				-0.7	
15	S01	Deduct for Overlap				-0.7	
16	PILLARS, ROCKER & FLOOR						
17	S01 R&I	RT Running board				1.0	
18	S01 R&I	LT Running board				1.0	
19	QUARTER PANEL						
20	Blnd	RT Quarter panel			s		2.2
21	* S01 Rpr	LT Quarter panel			s	3.0	3.1
22	S01	Add for Three Stage					2.2
23	R&I	Fuel door				0.3	
24	Refn	Fuel door					0.3
25		Add for Three Stage					0.1
26	R&I	RT Wheelhouse liner Escalade ESV				0.3	
27	R&I	LT Wheelhouse liner Escalade ESV				0.3	
28	* R&I	RT Qtr outlet vent				0.2	
29	* R&I	LT Qtr outlet vent				0.2	
30	* S01 Repl	RT Front molding	23227753	1	95.75	0.1	
31	Repl	LT Front molding	23227752	1	86.47	0.1	
32	R&I	RT Rear molding				0.4	
33	R&I	LT Rear molding				0.4	
34	* Rpr	RT Qtr glass w/o privacy tint - MASK				0.4	
35	* Rpr	LT Qtr glass w/o privacy tint - MASK				0.4	

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADi Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

36		S01	R&I	Lower qtr trim w/o power fold seat dune				0.6	
37		S01	R&I	Lower qtr trim w/o power seat dune				0.6	
38	REAR BODY								
39	*	S01	Rpr	Rear header				<u>3.0</u>	1.0
40		S01		Add for Three Stage					0.4
41		S01	R&I	Scuff plate w/o Suburban LS or Yukon XL SLT black				0.3	
42	*	S01	Rpr	RT Lower panel				<u>1.0</u>	0.3
43		S01		Add for Three Stage					0.1
44	*	S01	Rpr	LT Lower panel				<u>1.0</u>	0.3
45		S01		Add for Three Stage					0.1
46		S01	Blnd	RT Side panel					0.4
47		S01	Blnd	LT Side panel					0.4
48	*	S01	Repl	Case	15922078	1		<u>41.38</u>	
49	LIFT GATE								
50	*	S01	Rpr	Lift gate				<u>6.0</u>	2.3
51		S01		Overlap Major Adj. Panel					-0.4
52				Add for Three Stage					0.8
53		S01		Add for Edging					1.4
54		S01		Add for Three Stage					0.6
55			Repl	Handle	23339223	1	134.69	0.4	0.7
56		S01		Overlap Minor Panel					-0.2
57				Add for Three Stage					0.2
58			Repl	Applique 2nd design	23234931	1	161.12		
59	#		Repl	Nameplate "ESCALADE"		1	30.08	0.2	
60			R&I	Rear camera				0.2	
61	*		Rpr	<u>Lift gate glass GM w/privacy tint - MASK</u>				<u>0.5</u>	
62			R&I	Upper trim black				Incl.	
63			R&I	Lower trim panel w/o power lift gate black				0.6	
64	#		R&I	License bracket				0.2	
65		S01	R&I	Spoiler Escalade ESV				0.5	
66	REAR LAMPS								
67			R&I	RT Combo lamp assy 2nd design				0.3	
68			Repl	LT Combo lamp assy 2nd design	84211920	1	1,272.05	0.3	
69			R&I	RT License lamp				0.2	
70			R&I	LT License lamp				0.2	
71	REAR BUMPER								
72				O/H rear bumper				3.2	
73			Repl	Bumper cover	23326084	1	776.59	Incl.	3.2
74				Add for Three Stage					2.2
75				Add for radar sensor				0.4	
76			R&I	RT Side bracket				0.1	

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

77		Repl	LT Side bracket	22806431	1	21.85	0.1	
78		Repl	Lower molding	23224609	1	210.37	Incl.	
79		Repl	Bracket	22960925	1	50.56	Incl.	
80	S01	Repl	Deflector	84515908	1	326.55	Incl.	
81		R&I	RT Reflector				Incl.	
82		Repl	LT Reflector	84240626	1	55.71	Incl.	
83		Repl	Step pad	22960927	1	115.27	Incl.	
84		Repl	Access cover	84410295	1	127.17	Incl.	1.0
85			Add for Three Stage					0.4
86		Refn	Tow eye cap					0.2
87			Add for Three Stage					0.1
88		R&I	Impact bar w/power park brake				0.3	
89		R&I	Connector towing receptacle				0.2	
90		Repl	Harness 2nd design	23316326	1	122.48	Incl.	
91	*	S01	Repl Park sensor	23428268	4	830.00	Incl.	<u>0.0</u>
92	*	S01	Repl Impact bar w/o power park brake	22806381	1	<u>604.62</u>	0.3	
93	VEHICLE DIAGNOSTICS							
94	*	Repl	Pre-repair scan		1	m	<u>0.5</u>	
95	*	Repl	Post-repair scan		1	m	<u>0.5</u>	
96	MISCELLANEOUS OPERATIONS							
97	*	Repl	Cover car/bag		1	<u>5.00</u> X	0.2	
98	#		COVER VEHICLE FOR PRIMER		1	5.00 X	0.2	
99	#		ANTI CORROSIVE PRIME		1	15.00 T	0.5	
100	#	Refn	TINT TO MATCH - 3 STAGE					1.0
101	#		RESET ELECTRICS / D&R BATTERY		1		0.5	
102	#		WASH FOR REPAIR INSPECTION		1		0.5	
103	#		MASK JAMBS-RECESSED AREAS PRIMER		1	6.00 X	0.6	
104	#	S01	MASK JAMBS-RECESSED AREAS PAINT		1	10.00 X	1.0	
105	#		HARDWARE		1	20.00		
106	#		COLOR SAND AND BUFF		1		3.0	
107	#	Rpr	CLEAN COMPOUND RESIDUES				0.5	
108	#	Repl	CORROSION PROTECTION		1	15.00 T	0.2	
109	#		RUSTPROOF		1	10.00	0.2	
110	#	Repl	FLEX		1	12.00 T		
111	#		ADHESION PROMOTER		1	9.00		
112	#	Rpr	REMOVE OLD STRIPES & ADHESIVES				0.5	
113	#	Rpr	COLLISION ACCESS				0.5	
114	#	S01	ADDN'L PAINT AND MATERIALS REQ 24.9 HRS @ \$20 - 3 STAGE		1	498.00		
115	#	S01	SET UP AND MEASURE		1		2.0	
116	#	S01	Rpr PULL / ALIGN MASH				1.0 F	
117	#	S01	Rpr PINCH WELDS AFTER CLAMPING				0.5	0.5

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

118	#	S01	Repl	SEAM SEALER	1	30.00	T	0.5
119	#	S01	Repl	UNDERCOAT	1	8.00	T	
120	#	S01		CLEAN TO PRE-LOSS CONDITION	1			0.5
SUBTOTALS						5,705.71		52.3
								24.9

NOTES

Estimate Notes:

10075540 CMR: REGISTRY OF MOTOR VEHICLES

Claim number: listed above

Date :listed above

Appraiser: listed above

Important notice:

1. Your vehicle has sustained damage such that it may no longer meet the annual safety or emissions inspection standards. Your vehicle has such damage to the following item(s)
Damages: listed on appraisal above, any questions please call us
2. Massachusetts General Laws and 540 CMR 19.00 now require that the Certificate of Inspection be replaced by a Temporary Certificate of Inspection whenever a licensed damage appraiser determines that that a vehicle is damaged such that it may no longer meets the annual safety or emissions inspection standards.
3. The appraiser was unable to replace the Certificate of Inspection with a Temporary Certificate of Inspection due to the following:
 - a. Vehicle locked:
 - b. Other (explain): locked, or owner not present to give permission, or owner refused .any questions please call us
4. must arrange for the replacement of your Certificate of Inspection with a Temporary Certificate of Inspection immediately, or alternatively, have the vehicle repaired so that it may pass the safety and emissions standards and obtain a new Certificate of Inspection immediately You.
Failure to do so may result in a delay in settling your claim with the insurance company. The following are authorized to replace the Certificate of Inspection with a temporary Certificate of Inspection at no charge to you:
 - a. Any licensed Auto Damage Appraiser
 - b. Any Registry of Motor Vehicle Inspector
5. The Temporary Certificate of Inspection is valid for a period of 20 days. The damage which required the replacement of the Certificate of Inspection must be repaired before the expiration of the 20 day period.
Operating a vehicle without a valid Certificate of Inspection will subject the operator fines and insurance surcharges.
6. You must return a copy of this form signed by one of the authorized individuals specified in 4a or b above attesting to the replacement of the Certificate of Inspection with the Temporary Certificate to the address specified below.

I, Name Lic # Department date replaced
Certificate of Inspection, Serial number: Serial # all information listed in attached appraisal

With

Temporary Certificate of Inspection : Enter Serial #

7. Return this form to:

Name:

Street Address:

City, State Zip Code:

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				5,599.71
Body Labor	51.3 hrs	@	\$ 40.00 /hr	2,052.00
Paint Labor	24.9 hrs	@	\$ 40.00 /hr	996.00
Frame Labor	1.0 hrs	@	\$ 43.00 /hr	43.00
Paint Supplies	24.9 hrs	@	\$ 17.00 /hr	423.30
Miscellaneous				106.00
Subtotal				9,220.01
Sales Tax	\$ 6,103.01	@	6.2500 %	381.44
Total Cost of Repairs				9,601.45
Net Cost of Repairs				9,601.45

MyPriceLink Estimate ID / Quote ID:

524665753106915328 / 43095760

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Changed Items							
22	*	Rpr Lift gate				-5.0	-2.3
50	*	S01 Rpr Lift gate				6.0	2.3
23		Add for Three Stage					-1.6
52		S01 Add for Three Stage					0.8
59	*	Repl Park sensor	23428268	3	-622.50	Incl.	0.0
91	*	S01 Repl Park sensor	23428268	4	830.00	Incl.	0.0
71	#	MASK JAMBS-RECESSED AREAS PAINT		1	-6.00 X	-0.6	
104	#	S01 MASK JAMBS-RECESSED AREAS PAINT		1	10.00 X	1.0	
81	#	ADDN'L PAINT AND MATERIALS REQ 17.5 HRS @ \$20 - 3 STAGE		1	-350.00		
114	#	S01 ADDN'L PAINT AND MATERIALS REQ 24.9 HRS @ \$20 - 3 STAGE		1	498.00		
Deleted Items							
8		Blnd LT Quarter panel			s		-2.2
16		R&I RT Front molding				-0.1	
26		Overlap Minor Panel					0.2
49		R&I Deflector				Incl.	
Added Items							
6	ROOF						
7		S01 R&I R&I headliner				3.5	
8		S01 O/H luggage rack				4.0	
9		S01 R&I RT Side rail Escalade ESV				Incl.	
10		S01 Deduct for Overlap				-0.1	
11		S01 R&I LT Side rail Escalade ESV				Incl.	
12		S01 Deduct for Overlap				-0.1	
13		S01 R&I Rear headliner shale				1.7	
14		S01 Deduct for Overlap				-0.7	
15		S01 Deduct for Overlap				-0.7	
16	PILLARS, ROCKER & FLOOR						
17		S01 R&I RT Running board				1.0	
18		S01 R&I LT Running board				1.0	
21	*	S01 Rpr LT Quarter panel			s	3.0	3.1
22		S01 Add for Three Stage					2.2
30	*	S01 Repl RT Front molding	23227753	1	95.75	0.1	
36		S01 R&I Lower qtr trim w/o power fold seat dune				0.6	
37		S01 R&I Lower qtr trim w/o power seat dune				0.6	
38	REAR BODY						

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

39	*	S01	Rpr	Rear header				<u>3.0</u>	1.0
40		S01		Add for Three Stage					0.4
41		S01	R&I	Scuff plate w/o Suburban LS or Yukon XL SLT black				0.3	
42	*	S01	Rpr	RT Lower panel				<u>1.0</u>	0.3
43		S01		Add for Three Stage					0.1
44	*	S01	Rpr	LT Lower panel				<u>1.0</u>	0.3
45		S01		Add for Three Stage					0.1
46		S01	Blnd	RT Side panel					0.4
47		S01	Blnd	LT Side panel					0.4
48	*	S01	Repl	Case	15922078	1		<u>41.38</u>	
51		S01		Overlap Major Adj. Panel					-0.4
53		S01		Add for Edging					1.4
54		S01		Add for Three Stage					0.6
56		S01		Overlap Minor Panel					-0.2
65		S01	R&I	Spoiler Escalade ESV				0.5	
80		S01	Repl	Deflector	84515908	1	326.55	Incl.	
92	*	S01	Repl	Impact bar w/o power park brake	22806381	1	<u>604.62</u>	0.3	
115	#	S01		SET UP AND MEASURE		1		2.0	
116	#	S01	Rpr	PULL / ALIGN MASH				1.0 F	
117	#	S01	Rpr	PINCH WELDS AFTER CLAMPING				0.5	0.5
118	#	S01	Repl	SEAM SEALER		1	30.00 T	0.5	
119	#	S01	Repl	UNDERCOAT		1	8.00 T		
120	#	S01		CLEAN TO PRE-LOSS CONDITION		1		0.5	
				SUBTOTALS			1,465.80	25.8	7.4

CHANGES TO ADJUSTMENTS

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

TOTALS SUMMARY

Category	Basis		Rate	Cost \$
Parts				1,423.80
Body Labor	24.8 hrs	@	\$ 40.00 /hr	992.00
Paint Labor	7.4 hrs	@	\$ 40.00 /hr	296.00
Frame Labor	1.0 hrs	@	\$ 43.00 /hr	43.00
Paint Supplies	7.4 hrs	@	\$ 17.00 /hr	125.80
Miscellaneous				42.00
Subtotal				2,922.60
Sales Tax	\$ 1,587.60	@	6.2500 %	99.23
Total Supplement Amount				3,021.83
NET COST OF SUPPLEMENT				3,021.83

MyPriceLink Estimate ID / Quote ID:

524665753106915328 / 43095760

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	6,579.62	Francisco Enriquez
Supplement S01	3,021.83	Francisco Enriquez
Workfile Total:	\$ 9,601.45	
NET COST OF REPAIRS:	\$ 9,601.45	

" This document is neither an authorization to repair nor a guarantee of payment. Deductables, betterments and previous damage, if included in this document, will be deducted from any settlement with the vehicle owner. Supplements will be denied without prior approval from the appraiser. All supplemental damage found by the repairer must be inspected and documented by a representative of the insurance company before those repairs begin. All part price increases are subject to invoice verification. The vehicle owner must authorize all repairs." In accordance with ADALB Regulations, this appraisal was prepared and sworn to under the penalties of perjury. APPRAISER: _____ LICENSE: _____

PER MASSACHUSETTS REG. TITLE 212 CHAPTER 2.02(5), "THIS ESTIMATE HAS BEEN PREPARED AND SWORN TO UNDER THE PENALTIES OF PERJURY."

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1GA15, CCC Data Date 02/14/2019, and potentially other third party sources of data; and (b) the parts presented are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2019 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Supplement of Record 1 with Summary

Owner: PEREZ, EDGAR

Job Number: 19-13227

2015 CADI Escalade ESV Platinum 4WD 4D UTV 8-6.2L Flex Fuel Direct Gasoline Injection WHITE

FOR APPRAISAL QUESTIONS OR SUPPLEMENTS, PLEASE CALL THE APPRAISER ASSIGNED TO THE CLAIM

ANY GLASS PART PRICES, GLASS KITS AND/OR GLASS LABOR, IF INCLUDED IN THIS DOCUMENT, MAY BE BASED ON COMPETITIVE MARKET PRICING

THIS DOCUMENT IS NEITHER AN AUTHORIZATION TO REPAIR NOR A GUARANTEE OF PAYMENT. DEDUCTIBLES, BETTERMENTS, AND PREVIOUS DAMAGE, IF INCLUDED IN THIS DOCUMENT, WILL BE DEDUCTED FROM ANY SETTLEMENT WITH THE VEHICLE OWNER. SUPPLEMENTS WILL BE DENIED WITHOUT PRIOR APPROVAL FROM THE APPRAISER. ALL SUPPLEMENTAL DAMAGE FOUND BY THE REPAIRER MUST BE INSPECTED AND DOCUMENTED BY A REPRESENTATIVE OF THE INSURANCE COMPANY BEFORE THOSE REPAIRS CAN BEGIN. ALL PART PRICES ARE SUBJECT TO INVOICE VERIFICATION. THE VEHICLE OWNER MUST AUTHORIZE ALL REPAIRS.