


VEHICLE CONDITION REPORT



#94133525

Cosmetic Panel / paint = Blue
Minor Scratches / Dents = Yellow
Damaged / Dented = Black
Previous Body Repairs = Red
Rust = Orange

Please Note:

This inspection will not make comment on the alignment of any parts or body panels and will not be able to detect if any part of the vehicle is bent or out of its original shape. If you have any possible concerns with these items, please arrange an inspection by a registered smash repairer.

SafeBuy will note larger type damage and previous accident repairs to all vehicles when conducting a full comprehensive inspection.

However, smaller shopping size dents, scratches or hail damage will not be noted or guaranteed due to our mobile service encountering dirty, unwashed and wet vehicles and lighting conditions on site. It is the purchaser's responsibly to re - check the inspected vehicle personally, before settlement.

Interior			
Floor Covering / Carpet condition /drivers floor Dashboard	Fair Condition	Glove Box Air Vents	Ok
Door Trims / Roof Lining	General wear and tear	Sun Visors / Interior Light	Ok
Interior Mirror	Ok	Comb. Switch Hazard Switch	Ok
Front and Rear Wiper Washers	Front Ok	A/C Operation	Ok
Fan Speed Control Air Flow Control	Ok	Heater operation	Ok
Steering Wheel Grip Horn	Ok	Recycle Control Park Brake Operation	Ok
Sun Roof Operation	n/a	Pedal Rubbers	Ok
Front Seat Belts Rear Seat Belts	Ok	Windows Operation / Key Remote available	Ok
Rear Cover / Parcel Tray Fuel / Temp Gauges	Ok	Front Seat and Operation / General wear visible Rear Seat	Ok
Oil Pressure Light	NO	Warning Lights A.B.S.	no
Engine Light	No	SRS Lights	No
Hazard light	NO	Centre Consol	Ok

Added Notes:

Ecu scanned no codes found, no unusual lights on dash, Various interior trim plastics and seats show light scuffs and marks however not uncommon for the vehicle's age.

Road Test Report			
Inhibitor Switch Clutch Operation	Ok	Clutch Ride Brake Sink / Travel	OK
Brakes (ABS) Brake Shudder	No shudder	Steering Road Handling	Ok
Steering Vibrations Steering Wheel Alignment	No vibration	Gear Box Synchromesh 4x4 High and Low	n/a
Revs Under Load Gas Operation	Ok	Speedo / Odometer	Functioning Ok
Trip Meter / Cruise Control	Functioning ok	Turbo Charger	n/a
Driveshaft Vibrations Ride and Comfort	No vibration	Engine Performance / Engine Smoke	Ok
Trans Flare / Test Differential Whine	n/a	Speed Limit When Tested	60 kmh
Is 4WD Vehicles tested off road?	n/a	Vehicle's general drivability	Ok

Added Note:

No evident faults founds during inspection and in test drive