

Accident Evidence - Inspection Photo Report

Surveyor photo log (workshop sample)

Vehicle Registration: KA03PQ4455

Claim customer: Arjun Mehta

Photographs observed:

1. Rear bumper: light surface scratches.
2. No visible damage to front bumper, bonnet or headlamps.
3. No airbag deployment indicators.