

Accident Evidence - Inspection Photo Report

Surveyor photo log (workshop sample)

Vehicle Registration: KA05MN6789

Claim customer: Priya Nair

Photographs observed:

1. Front left door dented and scraped.
2. Left front fender crumpled.
3. Left side mirror assembly broken.