Water Service Call Record

Service Record

Customer: Oak Terrace Veterinary Clinic LLC. Claim reference: CLM-26-876731.

Visit: 2026-08-20. Address: 1539 Alder Court, Suite D.

Cause Assessment

The compression fitting above the utility alcove was spraying when the plumber arrived. The owner closed the local valve while the technician exposed the connection. A new fitting stopped the active flow and held the pressure test. The work order covers that fitting and test only; the technician did not remove flooring or open the corridor wall bases.

Work Notes

The service ticket was closed on 2026-08-20 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.