Utility Plant Condition Sheet

Assessment Record

Operator: Lakeshore Surgical Center LLC. Location: 1573 Alder Court, Suite F.

Claim CLM-26-366148; examination date 2026-08-31.

Condition and Repairability

The central utility compressor and vacuum unit were struck by water from the service spine. Inspection found wet electrical modules and winding failure in both units. The engineer's schedule lists matching output ratings and identifies the center as owner. The replacement proposal includes installation and disposal.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.