Utility Plant Condition Sheet

Assessment Record

Operator: Greenway Physical Therapy LLC. Location: 1522 Alder Court, Suite C.

Claim CLM-26-677883; examination date 2026-08-28.

Condition and Repairability

The therapy suite's utility compressor and cleaning vacuum were stored at the low end of the wet cupboard. Water crossed their motor vents. The repair shop found winding damage in both assemblies and lists replacement units with matching ratings. Ownership is recorded on the operator's fixed-asset sheet.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.