

IDARVIZHI DISASTER INTELLIGENCE REPORT

STATE : Andhra Pradesh
DISTRICT : Anantapur
YEAR : Year
DISASTER TYPE : Cyclone

OVERALL RISK SCORE : 0.35
SEVERITY INDEX : 55.44

1. Environmental Observations

Temperature C : 33.9
Rainfall Mm : 291.5
Humidity Pct : 52.1
Wind Speed Kmph : 86.4
Pressure Hpa : 1008.2
River Level M : 7.1
Soil Moisture Pct : 34.2
Population Density Sqkm : 10472
Hospital Access Index : 0.4
Evacuation Access Index : 0.84
Disaster Index : 55.44

2. Risk Interpretation

- > Elevated environmental stress indicators detected.
- > Weather parameters exceed historical seasonal averages.
- > Population exposure increases vulnerability.
- > Infrastructure readiness is moderate.
- > Immediate preparedness actions are recommended.

3. Advisory & Preparedness Measures

- > Activate district emergency operations center.
- > Issue public early warning advisories.
- > Deploy disaster response teams.
- > Prepare evacuation shelters.
- > Monitor updates every 3 hours.