

Scene Photograph Index and Measurement Log

A synthetic visual-evidence index. Graphic panels are placeholders, not recreations of actual photographs.

Document ID	Incident	Record type	Status
R3-EV-012	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

P01

Overall landing area

Beam on sled / scaffold

Synthetic image placeholder

P02

Link and keeper

Keeper visible as installed

Synthetic image placeholder

P03

Yoke pocket

No gross fracture visible

Synthetic image placeholder

P04

Window liner

Recovered with beam

Synthetic image placeholder

P05

Contact surfaces

As-found marks recorded

Synthetic image placeholder

P06

Upper stand

View partly obstructed

Synthetic image placeholder

Measurement log

Item	As-found observation	Measurement status	Status
Carrier beam	No gross fracture visible; landed across sled and scaffold platform.	Overall dimensions not re-measured before recovery.	Historical source fact / measurement open
Link	Recovered with beam and described as intact.	Critical wear and seating dimensions pending controlled inspection.	Historical source fact / pending
Keeper	Present and installed on recovered assembly.	Fit, deformation, and retained-pin clearance pending.	Historical source fact / pending
Yoke	No apparent gross damage in initial view.	Pocket geometry and contact-surface measurements pending.	Historical source fact / pending
Window liner	Small top-operator-side liner recovered with beam.	Pre-event location and attachment condition not documented in starter record.	Historical source fact / open

Original-file requirement

For a real investigation, upload the original image files with EXIF metadata and the scale/measurement method. This synthetic index is designed to prompt that request; it is not a substitute for imagery.