

Similar-Stand Comparison - R1, R2, R4, and R5

A synthetic comparison record based on the immediate action to inspect other stands. It provides context, not proof of R3's pre-event state.

Document ID	Incident	Record type	Status
R3-EV-014	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Comparison results

Stand	Keeper present	Balance position at inspection	Visual link seating	Disposition
R1	Yes	Lowered	Centered in visible yoke pocket	No gross anomaly
R2	Yes	Lowered	Centered; contact surfaces not measured	No gross anomaly
R4	Yes	Lowered	Slight visual asymmetry; engineering measurement requested	Follow-up
R5	Yes	Lowered	Centered in visible yoke pocket	No gross anomaly

Comparison limits

- All other balances were lowered before or during the immediate safety response.
- The comparison does not reproduce R3's raised, roll-removed, hydraulically bled configuration.
- Visual similarity is not a tolerance check.
- The R4 observation is an inspection lead, not evidence that it shares the R3 event mechanism.