

Preserved Video Review Log

A synthetic review of a partial camera view. It tests temporal corroboration without pretending that hidden geometry is visible.

Document ID	Incident	Record type	Status
R3-EV-017	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Camera and preservation

Camera	Coverage	Preserved interval	Limitation
Roughing-bay fixed camera - synthetic	Walking route, part of R3 stand, lower pit opening	12:50 PM-1:10 PM	Upper yoke/link interface obscured by stand structure; no useful audio

Observed sequence

Timestamp	Observation	Confidence	Status
1:03:09 PM	No person or crane hook visible within the immediate carrier-beam area.	High within camera field	Synthetic scenario fact
1:03:11 PM	Lower end of beam begins a small visible movement.	Moderate; upper connection hidden	Synthetic scenario fact
1:03:12 PM	Beam rotates and exits the visible support position.	High	Synthetic scenario fact
1:03:13 PM	Beam enters pit; dust / motion briefly obscures landing area.	High	Synthetic scenario fact
1:03:20 PM	Nearby personnel stop and move away from the stand.	High	Synthetic scenario fact

What video cannot answer

- Whether the link was fully seated in the yoke before motion began.
- Whether hydraulic or mechanical movement occurred inside the obscured upper assembly.
- Whether the small liner moved first.
- Exact fall geometry or component clearances.