

Witness Statement Packet

Two synthetic attributed accounts. The statements preserve observation limits and should not be blended into a single voice.

Document ID	Incident	Record type	Status
R3-EV-009	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Witness W-01 - contractor employee

Prompt	Statement
Position	Walking beside the R3 stand on the operator-side route; not inside the pit.
Observation	Saw the lower beam move slightly at one end, rotate, and then drop into the pit. Did not see a crane hook, rigging, or a person touching it.
Sound	Heard one metallic scrape followed by the impact.
Visibility limit	Could see the beam but not the upper link-to-yoke contact point.
Time confidence	Approximate; based on phone time checked after the event.

Witness W-02 - contractor employee

Prompt	Statement
Position	Several feet behind W-01 on the same walking route.
Observation	Looked toward the stand after hearing a scrape and saw the beam already moving downward. No crane motion was noticed.
Prior condition	Did not inspect the carrier beam or yoke before the event.
Visibility limit	Scaffold and stand structure partially blocked the lower landing area.
Uncertainty	Cannot say whether the small liner moved before, with, or after the beam.

Investigator note

Common points: falling beam, no observed person contact, no observed crane movement. Non-common points: W-01 reports seeing initial motion; W-02 begins observing after a sound. Preserve both accounts and their visibility limits.