

Scaffold Inspection and Mill-Pit Occupancy Record

A synthetic access record used to establish exposure, last-known occupancy, and post-impact scaffold status.

Document ID	Incident	Record type	Status
R3-EV-015	R3 carrier beam - 10/14/2024	Application test evidence	Synthetic / controlled

Access and inspection log

Time	Entry	Record source	Status
6:20 AM	R3 scaffold inspected and tagged available for planned configuration.	Competent-person scaffold tag	Synthetic scenario fact
6:45 AM-12:35 PM	Contractor crew entries and exits recorded intermittently for pit work.	Pit access sheet	Synthetic scenario fact
12:42 PM	Last recorded contractor exit before event.	Pit access sheet	Synthetic scenario fact
Approx. 1:03 PM	No personnel in pit when carrier beam fell.	Preliminary report and witnesses	Historical source fact
After event	Platform quarantined; impact damage assessment required before reuse.	Area-control log	Synthetic scenario fact

Exposure statement

The absence of personnel at the moment of impact prevented injury. Earlier occupancy beneath or near the potential fall path remains relevant to potential severity and control adequacy, but it does not show that worker action caused the fall.