Driver name	N/A
Delivery address	Evans Halshaw Vauxhall Wigan Sales Challenge Way Wigan LANCASHIRE WN5 0LD

AutoTrader

Vehicle Collection Report

Collection Address	Stratstone MINI Doncaster Wheatley Hall Road Doncaster SOUTH YORKSHIRE DN2 4PE

	Yes	No
Locking Wheel Nut	☒	☐
Spare Wheel / Tyre inflation / Run Flats	☒	☐
Jack	☐	☒
Tools	☐	☒
Charging Cable(s)	☐	☒
If yes, number of charging cables		
Sat Nav working	☒	☐
Vehicle Delivery Pack	☒	☐
Number Plates present & match	☒	☐
Any warning lights on	☐	☒
Headrests present	☒	☐
Parcel Shelf Present	☒	☐
V5 (Registration document) present	☒	☐
Number of Keys	2	
Mileage on Collection	27666	

	N/A	Empty	1/4	1/2	3/4	Full
Fuel	☐	☒	☐	☐	☐	☐
Charge	☒	☐	☐	☐	☐	☐

Notes

Do you agree with the above information Yes ☒ No ☐

Conditions Vehicle checked in

Weather ☐ Wet ☒ Dry **Light** ☒ Good ☐ Bad

Photos Taken

LH Side	Yes ☒	No ☐	**RH side**	Yes ☒	No ☐
Front	Yes ☒	No ☐	**Back**	Yes ☒	No ☐
Dashboard	Yes ☒	No ☐	**Keys**	Yes ☒	No ☐
Number plates	Yes ☒	No ☐			

Order Number	m3ny6cR7a9gxoGMbOyUy
Reg. Number	KO67FYS
Make	MERCEDES-BENZ
Model	A CLASS DIESEL HATCHBACK
Specification	Blue
Colour	Blue
Trim	
Factory Fitted Options	
Dealer Fitted Accessories	
Chasis Number	WDD1760082J748092

Collection Acknowledgment

	Yes	No
Was the vehicle clean internally?	☒	☐
Was the vehicle clean externally?	☒	☐
Was the vehicle free of damage internally?	☒	☐
Was the vehicle free of damage externally?	☐	☒
Was the vehicle collected from the right place at the right time?	☒	☐
Was the manufacturers handbook/service book in the vehicle?	☒	☐
Mats in place?	☒	☐
Hand over accepted	☒	☐



Key:

- damage with photos
- damage without photos
- copied damages



Disclaimer

If the vehicle is inspected in poor weather conditions, or is excessively soiled, it may not be possible to produce an accurate inspection report. In such instances the right is reserved to recharge for any damage not recorded at the time of hand over. Any missing items will also be rechargeable. By signing this document, you are agreeing that as far as you are aware all personal, business and professional items have been removed, you agree with the recorded details of the vehicle condition and the stated mileage is correct.
I confirm that I agree with the details recorded.

Signed (Customer)	Customer name N/A	Date	06/03/2025 15:54:32
	Signed for by Reece		
	Have you been shown the details recorded by the driver?		Yes ☒ No ☐
Signed (Delivery Agent)	Delivery Agent name rezakhoshgoftar	Date	06/03/2025 15:54:41
	Estimated time of arrival	Date	06/03/2025 15:54:00

Damage
Off Side Doors
Front Door
Chip > Single

Damage
Near Side Front Wing
Front Bumper
Scratch > Single

Damage

Near Side Doors
Front Door
Scratch > Single

Damage
Rear Bumper and Valance
Rear Bumper
Scratch > Single

Damage
Near Side Front Wheel
Wheel
Steel > Rim > Damaged

Damage
Off Side Front Wheel
Wheel
Steel > Rim > Damaged

Damage
Near Side Rear Wheel
Wheel
Steel > Rim > Damaged

Damage
Off Side Rear Wheel
Wheel
Steel > Rim > Damaged

Damage
Near Side Rear Quarter
Wing
Scratch > Single

Picture

Picture

Picture


Picture


Picture