



CENTRAL COAST SECTOR 4

Clean Room Data Ingress | Statutory Compliance Verification (POEO / AS 2870)

PIPELINE LIVE

SPATIAL ACCURACY (GSD)



0.82 cm/px

Sub-centimeter photogrammetry verified

POEO ACT COMPLIANCE



PASSED

0 Active Environmental Breaches

STRUCTURAL RISK (AS 2870)



MONITORING

1 Soil Movement Anomaly Flagged




GIS SPATIAL INTELLIGENCE & BOUNDARY POLYGON

GIS SPATIAL OVERLAY:

Satellite

Thermal


Mesh Vector





FOUNDATION DISPLACEMENT DELTA METRICS (mm) — 6-MONTH INTERVAL

TOLERANCE LIMIT: ±5.0mm



M1: 1.2mm M2: 1.4mm M3: 1.8mm M4: 2.1mm M5: 2mm M6: 2.1mm

CLEAN ROOM AUDIT TRAIL — CENTRAL COAST SECTOR 4

ISO/IEC 27037 STANDARD

```
[2026-07-23 15:00:01 AEST] Ingress Hash Verified: 0x8f2a...c4e9
[2026-07-23 15:02:14 AEST] Telemetry stream locked: Ground elevation baseline recorded.
[2026-07-23 15:05:30 AEST] Section 120 POEO Act compliance check executed: PASS.
[2026-07-23 15:08:12 AEST] AS 2870 Foundation displacement delta: +2.1mm (Within tolerance threshold).
// End of active evidence buffer block
```

 Forensic Artifacts

Download fully structured forensic documentation, statutory breach analyses, and spatial maps formatted for court submission.

 **Export Evidence Package**