

BUILDING INSPECTION REPORT

Property: Sunshine Apartments, Block A
Date: April 25, 2026

Observations:

1. Living Room: Visible water staining on the ceiling near the north window.

DDR Report Generator

Upload your inspection and thermal reports below to generate a formatted DOCX report.

Inspection Report (PDF)

Choose File

No file chosen

Thermal Report (PDF)

Choose File

No file chosen

Generate Report

2. Master Bedroom: Minor cracks observed in the plaster on the west wall.
3. Roof: Blocked gutters on the northeast corner causing overflow during rain.
4. Kitchen: Cabinet hinges are loose and need adjustment.