



## Quotation: PQ202509-74E373AD

Quotation Date: 17/09/2025

Valid Until: 17/10/2025

### client 1

0706707144, 121212, Nairobi  
Laser Printer X100  
Email: mburudominic381@gmail.com  
Phone: +254706526569

### client 1

0706707144  
Phone: +254706526569  
Email: mburudominic381@gmail.com  
Website: <https://flotto.jaytechprinterimports.co.ke>

### Project Description

#### - Entree (10.0m<sup>2</sup> walls, 3.0m<sup>2</sup> ceiling):

- Two Coats: 3.3m<sup>2</sup> ceiling area

#### - Eetkamer (17.0m<sup>2</sup> walls, 6.0m<sup>2</sup> ceiling):

- One Coat: 17.3m<sup>2</sup> wall area

#### - Woonkamer (51.0m<sup>2</sup> walls, 48.0m<sup>2</sup> ceiling):

- One Coat: 51.2m<sup>2</sup> wall area

#### - Keuken (14.0m<sup>2</sup> walls, 6.0m<sup>2</sup> ceiling):

- Two Coats: 6.0m<sup>2</sup> ceiling area

#### - Zijkamer (16.0m<sup>2</sup> walls, 7.0m<sup>2</sup> ceiling):

- Two Coats: 16.3m<sup>2</sup> wall area

#### - Slaapkamer 1 (22.0m<sup>2</sup> walls, 9.0m<sup>2</sup> ceiling):

- One Coat: 21.6m<sup>2</sup> wall area

#### - Slaapkamer 2 (20.0m<sup>2</sup> walls, 8.0m<sup>2</sup> ceiling):

- One Coat: 8.4m<sup>2</sup> ceiling area

#### - Badkamer (12.0m<sup>2</sup> walls, 5.0m<sup>2</sup> ceiling):

- Priming: 5.0m<sup>2</sup> ceiling area

#### - Waskamer (12.0m<sup>2</sup> walls, 5.0m<sup>2</sup> ceiling):

- One Coat: 4.8m<sup>2</sup> ceiling area

#### - Hal (9.0m<sup>2</sup> walls, 4.0m<sup>2</sup> ceiling):

- One Coat: 3.6m<sup>2</sup> ceiling area

#### - Interior Work:

- Stairs: Stair (Qty: 1)
  - Unit Price: £25.00

**- Exterior Work:**

• **Turnwindows:** Turn Window (Qty: 1)

- Condition: New/Pre-primed
- Unit Price: £75.00

• **Preparation Steps:**

1. Clean surface (dust and degrease with sugar soap)
2. Light sanding to key the surface
3. Prime if bare wood (skip if factory-primed and in good condition)
4. Apply topcoat

**- Special Jobs & Conditions:**

• **Water Damage/Leak Repair:** Water Damage/Leak Repair (Qty: 1 job)

- Unit Price: £150.00
- Total Cost: £150.00
- Materials included in price

• **Process Steps for Water Damage/Leak Repair:**

1. Identify and dry affected area completely (use moisture meter if needed)
2. Scrape off bubbling/loose paint
3. Treat any mold/mildew with anti-fungal wash
4. Fill any damaged plaster
5. Sand smooth and apply stain-block primer

**Summary Table**

Quantity	Description	Amount (excl. VAT)
3.0	Entree - Ceiling - Painting (2 Coats)	EUR 27.71
17.0	Eetkamer - Walls - Painting (1 Coat)	EUR 104.04
51.0	Woonkamer - Walls - Painting (1 Coat)	EUR 307.14
6.0	Keuken - Ceiling - Painting (2 Coats)	EUR 51.00
16.0	Zijkamer - Walls - Painting (2 Coats)	EUR 155.04
22.0	Slaapkamer 1 - Walls - Painting (1 Coat)	EUR 129.60
8.0	Slaapkamer 2 - Ceiling - Painting (1 Coat)	EUR 46.20
5.0	Badkamer - Ceiling - Priming	EUR 27.50
5.0	Waskamer - Ceiling - Painting (1 Coat)	EUR 26.40
4.0	Hal - Ceiling - Painting (1 Coat)	EUR 19.80
1.0	Interior - Stair	EUR 25.00
1.0	Exterior - Turn Window	EUR 75.00
1.0	Special Job - Water Damage/Leak Repair	EUR 150.00
<b>Total excl. VAT</b>		<b>EUR 1144.43</b>
<b>VAT (20%)</b>		<b>EUR 228.89</b>
<b>Total incl. VAT</b>		<b>EUR 1373.32</b>

The price includes all materials, labor, travel costs, and leaving the site clean.

This quotation is valid until 17/10/2025. Please return a signed copy if you wish to proceed.

---

**Client Acceptance:**

By signing below, I accept the terms and conditions of this quotation.

Digital Signature: \_\_\_\_\_

Date: \_\_\_\_\_