In360° View
Inventories · Inspections · Floorplans

CHECK-IN INVENTORY REPORT

42 Ashcombe Road

Flat 2, Bristol
BS7 9QT



REPORT REFERENCE	CI-204831
INSPECTION DATE	14 September 2026
INSPECTED BY	Helen Carter
TENANT PRESENT	Yes
ROOMS INSPECTED	4
ITEMS LISTED	16

INSIDE THIS REPORT
4 rooms inspected · 16 items listed · 8 photographs · 3 meter readings · 4 key sets · Disclaimer & terms

Signed and locked 14 Sept 2026, 13:42

REPORT DETAILS

REPORT TYPE
Check-In

REPORT REFERENCE
CI-204831

INSPECTION DATE
14 September 2026

PROPERTY REFERENCE
PR-104829

INSPECTED BY
Helen Carter

CLERK CONTACT
helen.carter@in360view.co.uk

TENANT PRESENT
Yes

WEATHER / CONDITIONS
Dry, overcast, 17°C

PROPERTY & PARTIES

PROPERTY TYPE
Victorian terrace

FURNISHING
Part furnished

BEDROOMS
2

BATHROOMS
1

LANDLORD
Marcus Wainwright

LANDLORD EMAIL
m.wainwright@example.co.uk

TENANT
Priya Desai

TENANT EMAIL
p.desai@example.com

OVERALL SUMMARY

Condition: Good | Cleanliness: Clean

SUMMARY

The property was presented in good decorative order throughout and professionally cleaned prior to the inspection. All rooms were accessible and the tenant attended for the full inspection.

MAINTENANCE ISSUES

Kitchen extractor fan is noisy in operation and should be serviced.
Hairline crack to the plaster above the living room window — monitor only.

TENANT OBSERVATIONS

Tenant noted a small chip to the bath enamel and asked that it be recorded at check-in.

METER READINGS

Electricity	Reading: 41872.4 · Serial: K14G 882301 · Cupboard, entrance hall
Gas	Reading: 09318 · Serial: G4 7729114 · External box, front elevation
Water	Reading: 00412 · Serial: W-5521884 · Pavement stopcock

KEYS

2 × Front door — Yale	Issued to tenant
2 × Front door — mortice	Issued to tenant
1 × Window key	Left in kitchen drawer
1 × Communal bin store fob	

FRONT ELEVATION & ENTRANCE HALL

3 items

Good Clean

Painted timber front door with Yale and mortice locks. Hall laid with engineered oak, light scuffing consistent with normal use.

Front door & furniture	Good Clean White painted timber door, chrome handle, working letterplate.
Hall flooring	Good Clean Engineered oak, light scuffing near the threshold.
Ceiling & light fitting	Excellent Clean Pendant fitting with shade, bulb working.

Front elevation & entrance hall — general photographs



Front elevation of the property from the street



Front door and entrance approach

KITCHEN / DINER

5 items

Good Clean

Fitted grey shaker units with laminate worktops. All appliances present and apparently operational on the day.

Base & wall units (x11)	Good Clean Grey shaker doors, all hinges sound. Minor edge wear to the unit beside the oven.
Worktops	Good Clean Oak-effect laminate, one 30mm scorch mark to the right of the hob. Note: Recorded at check-in.
Oven & hob	Good Clean Four-ring gas hob, single electric oven. Interior clean.
Extractor fan	Fair Generally clean Operational but noisy on all speeds. Note: Reported to the landlord.
Fridge freezer	Good Clean Freestanding, defrosted and clean.

Kitchen / diner — general photographs



Kitchen looking towards the window



Worktop and splashback

LIVING ROOM

4 items

Good Clean

Bay window to the front with working sash. Carpet professionally cleaned.


Carpet	Good Clean Grey twist pile, no visible marks.
Walls & decoration	Good Clean Magnolia emulsion. Hairline crack above the window — monitor.
Two-seat sofa	Good Clean Grey fabric, fire label attached and intact.

Radiator	Good · Clean Double panel, both valves turn freely.

Living room — general photographs



Living room from the doorway



Bay window and decorative surround

BATHROOM

4 items

Fair · Clean

White three-piece suite. Sealant renewed prior to the tenancy.

Bath & shower over	Fair · Clean 10mm chip to the enamel beside the hot tap. Shower runs hot and cold. Note: Raised by the tenant at check-in.
WC	Good · Clean Close-coupled, flushes correctly, seat secure.
Basin & pedestal	Good · Clean No chips, both taps run freely.
Extractor & window	Good · Clean Extractor operational, obscured window opens and locks.

Bathroom — general photographs



Bathroom suite



Chip to the bath enamel, near the taps

DECLARATION & SIGNATURES


The parties named below confirm that they have read this report and agree that it is a fair and accurate record of the condition and contents of the property on the date of inspection. Once signed, this report is locked and cannot be altered.

CLERK

Helen Carter

helen.carter@in360view.co.uk

Signed 14 Sept 2026, 13:40




TENANT

Priya Desai

p.desai@example.com

Signed 14 Sept 2026, 13:40



Document locked 14 Sept 2026, 13:42 — this is the final signed version.

DISCLAIMER

This report is a record of the visual condition and contents of the property on the date of inspection only. It is prepared for the use of the landlord, the tenant and their appointed agent, and should be read together with the tenancy agreement.

Not a structural survey

The inspection is visual and non-invasive. It is not a structural survey, valuation, or condition report on the fabric of the building, and no comment is made on the adequacy of construction, damp, subsidence, insulation or drainage.

Nothing moved or dismantled

Furniture, floor coverings, stored goods and heavy appliances are not moved, lifted or dismantled. Surfaces beneath and behind them are not inspected and no opinion is given on their condition.

Inaccessible areas

Lofts, cellars, outbuildings, locked rooms, sealed cupboards and any area not safely reachable from floor level are excluded unless specifically recorded in this report.

Not a compliance or safety certificate

This report is not a gas, electrical, EPC, legionella, fire safety or furniture-regulations certificate. Alarms, appliances, heating and services are only tested where this report expressly says they were, and then only for apparent operation on the day.

Condition and cleanliness grading

Condition and cleanliness are graded by visual assessment against the standard expected for a property of this type, age and furnishing level. Terms such as “good” or “clean” are comparative descriptions, not warranties.

Photographs

Photographs support the written entries and are illustrative rather than exhaustive. The absence of a photograph does not imply the absence of an entry, and colour may vary with lighting conditions.

Items and quantities

Contents are listed as presented. No comment is made on ownership, provenance, authenticity, age or value, and electrical or gas items are not PAT tested unless stated.

Impartiality

The inspecting clerk attends as an impartial third party and has no interest in the property or in the outcome of any deposit claim.

TERMS & CONDITIONS

The following terms apply to the preparation, delivery and use of this report. Instructing In360View, attending the inspection or relying on this report constitutes acceptance of them.

1. Scope of service

In360View records the condition and contents of the property at the date and time of the inspection. The service does not include cleaning, repairs, removals, key cutting, compliance testing or dispute representation.

2. Access and preparation

The instructing party is responsible for providing safe and unobstructed access, working lighting and power, and confirming whether the property is occupied. Where access is refused, delayed by more than 30 minutes, or unsafe, the visit may be abandoned and a call-out charge may apply.

3. Checking period

Any request to correct or amend this report must be made in writing within seven (7) days of the report being issued. After that period the report is taken as agreed by all parties who received it, whether signed or not.

4. Signatures and locking

Once signed by a party the report is locked and no entry can be altered. A subsequent correction is issued as a separate addendum that references the original report.

5. Photographs, data and retention

Photographs, signatures and report data are stored securely and retained for six (6) years to support deposit and legal proceedings, then deleted. Personal data is processed as controller by the instructing party and as processor by In360View in line with UK GDPR; a subject access request should be sent to the instructing party in the first instance.

6. Use of the report

The report may be shared with the landlord, tenant, appointed agent, a deposit scheme adjudicator or a court. It may not be edited, re-branded, sold or published in part where doing so would misrepresent its findings.

7. Liability

In360View accepts liability for the accuracy of the entries recorded, but not for matters excluded by the disclaimer above, for latent or concealed defects, or for any loss of rent, deposit award or consequential loss. Save for death or personal injury caused by negligence, total liability is limited to the fee paid for the inspection.

8. Fees and cancellation

Fees are payable within 14 days of invoice. Cancellation with less than 24 hours' notice may be charged at 50% of the agreed fee, and an abandoned visit at the full fee.

9. Complaints

Complaints should be raised in writing and will be acknowledged within five working days and answered within 21 days.

10. Governing law

These terms are governed by the laws of England and Wales and are subject to the exclusive jurisdiction of its courts.