and the same and	AMCO ID/PID MCO TEST REPORT							- 14	SATR-NDE-2008 Rov-1			101	(2)			10		<del></del>		
NON -DESTRUCTIVE TESTING TESTING (NDT) REQUEST / NDT ASSESSMENT / INTERPRETATION REPORT								NDT Category Acceptance Criteria				BTFI CRM Number			RTFI Assessment Number	T	1	Assessment Date:		
ROJECT T	TTLE:- EAST WEST P	IPELINE PROJECT			4		1	10% / 100%		ASME 831.3 .		1.38	40	1404140E						
Fecility/Location: PS-02 LAYDOWN YARD  TYPE OF NON DESTRUCTIVE TESTING REQUESTED - RADIOGRAPHY TESTING							100% / 10 %		49	4044841495				SEG-EWPL-ZEP-0011			3-Jul-23			
							.0 week	WBS / BI / JO	Prime Contractor / Sub co		ntractor	NDT Contractor:			RWP No.			RWP Validity		
ATIP NO	IP NO SATIP ACTIVITY ITEM NO INSPECTION LEVEL						2149	AL.							*					
ATIP-NDE-	3.1		Contractor			Aramco		10-01201	7025	SINOPEC		ZEPPELINE		7996			18-Nov-23			
RT-01	l w		W/R	MIR		WIR 174		- Cate	del allera											
		The state of the s	-		-		NON-DES	TRUCTIVE TESTI	NG TESTING (NDT)REQU	JEST / NDT ASS	ESSMENT / INTERP	10.00	-							
	DRAWING & ISOMETRIC NUMBER	LINE NUMBER	DIA	THK WELD NUMBER	WELD		H Dain	WEST DIVID		RT	LOCATION	NDT AGENCY COMMENTS			PRIME CONTRACTOR COMMENTS			SAUDI ARAMCO ASSESSMENT		
SI.No		SKETCH NUMBER	(Inch)		SPOOL No	WELDER ID	WELDING PROCESS	NDT LOG NUMBER		LOCATION MARKERS	ACC	RESHOOT	COMMENTS	AGREE	COMMENTS	NO.OF FILMS	AGREE	COMMENTS		
1	XB-321424-001- 00	48"-P-1483- 6CS1P	48"	26.97	FW-03 IP BSR	SP-01	Side-A:- Root/Hot/Fill/ Cap:- SEG-EW-003 IP3 Side-B:- Root/Hot/Fill/Cap SEG-EW-004 IP1	GTAW SMAW	SEG-RT-0047	2002	FULL	V		100 qq-qq1 (width) ymm	1	138-138/2 142-142/2	12			
2	XB-321424-001- 00	48"-P-1483- 6CS1P	48"	26.97	FW-24 IP BSR	SP-15	Side-A:- Root/Hot/Fill/ Cap:- SEG-EW-010 Side-B:- Root/Hot/Fill/Cap SEG-EW-001 IP3	GTAW SMAW	SEG-RT-0048		FULL									
							LEAD AND LEAD AND ADDRESS OF THE ADD			=										
					-				- ni				101							
							to the second								-					
							-	4	(6)			14:0	-							
								337.49	177	1										
								- 71	ľ	* 15								11		
					-		-1/37				-						/			
							1.30		- (8)	19		-		TOTAL JOINTS=		TOTAL FILMS=	12			
	NON -DESTRU	CTIVE TESTING	TESTING	(NDT) F	REQUEST		1 112.00				NDT ASSE	ESSMENT	INTE	RPRETATION				4-1	1 1 5	
S G	CONST. Representative Mr.LI		Pa-	Date 3-Jul-23	NC	T SERVICE	PROVIDER			PRIME CONTRACTOR				SAUDI ARAMCO/ID/ITSD /CNDT&PSU			CNDT&PSU			
	NDT Coordinator / QC Inspector		Mr. TALH, J. Olh		Other	3-Jul-23	RTFI NAME	ER A	HMED	RTFI NAME			NOT ARABIA CO. LTD			RTFI NAME ()			5 JUL COP	
SON	QC Supervisor		Mr. SHIRAZ		- 4	3-Jul-23	SA RTFI NUMBER	RTF1: ZGULF CO. LTD. SA RTFI NUMBE		RSA	1	1 20		SA RTFI NUMBER		1	Hans.			
AUDI ARAMCO PID Representative: Mr. FAISAL			21			LIN SYSTEM	SERVICES		sig	-		2001	0	SIG	CHI	TE	11100			
all:	tisal.mughal@aramco.	som		1	11		DATE	TILL T	= 1/2=		DATE	1200	-	hund xx	7	DATE	311	1		

SEG RT REQUEST

Soudi Aramco: Company General Use:

page 1 of 1