Site Visit Report

The team visited the north yard on 12 October 2026 to check the new storage area and the loading bays.




Figure 1: the north yard from the gate.

Status: approved by the site manager.

Inspector	
Company stamp	

تمت زيارة الموقع والتأكد من جاهزية منطقة التخزين الجديدة.

Next steps

The loading bays will be painted before the end of the month.

Signed:



مع خالص الشكر لفريق العمل.