

Rapporto System Information disponibile in: 06/30/26 01:29:04

Nome sistema: KATARR0

[Risorse di sistema]

Elemento	Valore
Nome SO	Microsoft Windows 11 Pro
Versione	10.0.26200 build 26200
Descrizione altro SO	Non disponibile
Produttore SO	Microsoft Corporation
Nome sistema	KATARR0
Produttore sistema	Micro-Star International Co., Ltd.
Modello sistema	MS-7E26
Tipo sistema	PC basato su x64
SKU sistema	To be filled by O.E.M.
Processore	AMD Ryzen 7 7800X3D 8-Core Processor, 4201 Mhz, 8 core, 16 processori logici
Versione/data BIOS	American Megatrends International, LLC. 1.A0, 27/03/2024
Versione SMBIOS	3.6
Versione controller integrato	255.255
Modalità BIOSUEFI	
Produttore scheda di base	Micro-Star International Co., Ltd.
Prodotto scheda di base	B650 GAMING PLUS WIFI (MS-7E26)
Versione scheda di base	1.0
Ruolo piattaforma	Desktop
Stato avvio protetto	Attivato
Configurazione PCR7	Necessaria elevazione dei privilegi per la visualizzazione
Directory Windows	C:\WINDOWS
Directory System	C:\WINDOWS\system32
Periferica di avvio	\Device\HarddiskVolume1
Locale	Italia
Hardware Abstraction Layer	Versione = "10.0.26100.1"
Nome utente	KATARR0\happy
Fuso orario	ora legale Europa occidentale
Memoria fisica installata (RAM)	32,0 GB
Memoria fisica totale	31,2 GB
Memoria fisica disponibile	19,7 GB
Memoria virtuale totale	33,9 GB
Memoria virtuale disponibile	14,5 GB

[Archiviazione]

[Unità]

Elemento	Valore
Unità disco	C:
Descrizione	Disco rigido locale
Compresso	No

File System NTFS
Dimensione 930,57 GB (999.190.163.456 Byte)
Spazio libero 89,29 GB (95.874.203.648 Byte)
Nome volume
Numero di serie volume D27822B9

● FULL FORENSIC REPORT

AMD Ryzen 7 7800X3D

Solid performance across all three test stages.

OVERALL SCORE

85

B BALANCED

CPU DECAY

0.0%

stable

GPU DECAY

2.2%

fluctuating

PATH TRACING

15.8 SPS

100/100 consistency

RESULT SNAPSHOT

85_{/100}

BALANCED

B SYSTEM GRADE

GRADE

100/100

THERMAL

99/100

DURATION

3M 20S

ANSWER FIRST

AMD Ryzen 7 7800X3D and NVIDIA GeForce RTX 4070 SUPER scored 85/100 with grade B in a real browser benchmark. Solid performance across all three test stages. This result is from the latest local benchmark payload until enough clean crowd samples are aggregated.

BOTTLENECK VERDICT

This CPU and GPU pairing looks well balanced under sustained browser benchmark load.

STABILITY UNDER LOAD

Path tracing measured 16 SPS at 100/100 consistency. CPU decay is 0.0% and GPU decay is 2.2%.

THERMAL READ

Thermals look healthy at 99/100, with low sustained decay across the measured stages.

SCORE MEANING

Overall score is 85/100 with system grade B. The score combines sustained CPU decay, GPU decay, path-tracing throughput, and consistency.

Data source: real browser benchmark telemetry from CPU stress, GPU compute, and WebGL path tracing. Fresh local result: waiting for enough clean crowd samples to enter the public aggregate. No anomaly flags are attached to this displayed result.

PERSONAL DIAGNOSIS

SEVERITY: CLEAN

CONFIDENCE: 76%

HEALTHY

Save this run as your clean baseline

Decay stayed controlled and the report did not find a dominant limiter.

AMD Ryzen 7 7800X3D sustained 27164617M ops/s with 0.0% decay.

NVIDIA GeForce RTX 4070 SUPER accepted 659.93B work/s at 100/100 pressure stability.

Path tracing measured 15.8 SPS at 100/100 consistency.

Thermal health is 99/100 and CPU/GPU synergy is 100/100.

THREE-STAGE STRESS TEST

STAGE 1 - CPU STRESS

STABLE

27164.6B ops/s

SUSTAINED THROUGHPUT

THREADS

16

PEAK

-

WARM-UP

PEAK LOAD

SUSTAINED

SUSTAINED DECAY

0.0%

STAGE 2 - GPU RASTER

FLUCTUATING

97 /100

PRESSURE SCORE

RASTER WORK

659.93B work/s

FRAME PACING

87.6ms

WARM-UP

PEAK LOAD

SUSTAINED

STAGE 3 - PATH TRACING

STABLE

15.8 SPS

SAMPLES PER SECOND

CONSISTENCY

100/100

TARGET

150 SAMPLES

WARM-UP

PEAK LOAD

SUSTAINED

SUSTAINED DECAY

0.0%

GPU PRESSURE DIAGNOSIS

 PRESSURE
SCORE

97/100

ELITE

RASTER WORK

659.93B

sustained work/s

 STABLE
CEILING

 32.768 x
7113

sustaining phase

FRAME PACING

87.6ms

2 FPS low

BACKEND

WEBGPU

STABILITY

100/100

VRAM PRESSURE

MODERATE

GAMING

The flythrough stayed at 2 FPS low while pressure ran behind it. That is the pacing signal, not the score.

RENDERING

Sustained raster pressure reached 659.93B work/s, which is the useful V2 throughput signal.

THERMALS

GPU decay stayed near 2.2%, so this looks more like a stable baseline than a thermal collapse.

TRUST

WebGPU backend was active, so this run has the strongest browser-side pressure signal.

FIX PRIORITY

This is a strong Stage 2 baseline. Save it and compare future driver, cooling, or dust changes against this run.

SCORE BREAKDOWN

SCORE FORMULA

FINAL SCORE

CPU throttle

-0

out of 30 pts

GPU throttle

-2.2

out of 30 pts

PT decay

-0

out of 15 pts

PT consistency

-0

out of 25 pts

PT throughput

-14.7

out of 40 pts

SYSTEM BALANCE

SYSTEM BALANCE

100 /100

Exceptional CPU-GPU pairing

CPU contribution

GPU contribution

THERMAL INTEGRITY

99 /100

Cooling is under control

CPU health

30% 100

GPU health

40% 97

PT health

30% 100

SILICON DOCTOR

SILICON DOCTOR

SYSTEM DIAGNOSIS

