WORK ORDER - FLAT BED TRAILER -REPAIR

| Α | JOB NU | MBER: FBT-R-25-002 | В | AXEL DETAIL: YORK Triaxle |
|---|-----------|--|-------|----------------------------|
| С | NAME (| OF THE CLIENT: Dynamic | D | CHASSIS NUMBER:DLT 0967 |
| Ε | TARGET | DATE: 31.01.2025 | F | PRIORITY STATUS: V. Urgent |
| | | | WP | LX 0404 |
| 1 | TRAILER R | REPAIRS AND SPECIAL FEATURES: | | |
| - | 1.1 | IF AN INSUARANCE REPAIR -ATTACH THE APPROVED | DEL | DAID LICT. |
| | 1.1 | IF AN INSUARANCE REPAIR -ATTACH THE APPROVEL | J NEI | AIN LIST. |
| | 1.2 | IF IT IS A NORMAL REPAIR LIST OUT THE ACTIVITIES: | : | |
| | 1.2.1 | Identify & correct all the repairs | | |
| | | | | |
| - | 1.2.2 | Check & correct all electrical & pneumatic lines | | |
| | 1.2.3 | Axle repair & alignment test if required | | |
| _ | | | | |
| - | 1.2.4 | Sand Blasting & painting | | |
| - | 1.2.5 | | | |
| | | | | |
| | | | | |
| 2 PAINTING DETAILS: | | | | |
| | 2.1 | COLOUR AND DESIGN: Golden Yellow | | |
| | | COLOUR MILE DESIGN. CONCENTION | | |
| | 2.2 | ANY OTHER: | | |
| | | | | |
| _ | | | | |
| | | | | |
| | | | | |
| | | | | |
| _ | | | | |
| WORKSHOP MANAGER: FACTORY MANAGER: FACTORY MANAGER: | | | | |
| | Worthorn | The following the first th | | |
| | | | | DATE: 10.01.2025 |
| | COPIES: | 1. ALL SUPERVISORS. | | |
| | | 2. COSTING & QUALITY ASSUARANCE. | | |
| | | 3. STORES. | | |
| | | 4. RELEVENT NOTICE BOARDS. | | |
| | | 5. RESPONSIBLE OFFICE: MR. HEMANTHA 6. ISO OFFICER/MR. CHATHLIBANGA | | |
| | | 6. ISO OFFICER/ MR. CHATHURANGA | | |
| _ | | | | |