

## WORK ORDER - FLAT BED TRAILER -REPAIR

A JOB NUMBER: FBT-R-25-001 B AXEL DETAIL: Fuwa Tandem  
C NAME OF THE CLIENT: Dynamic D CHASSIS NUMBER:T33460-09  
E TARGET DATE: 16.01.2025 F PRIORITY STATUS: V. Urgent

WP LX 0985

### 1 TRAILER REPAIRS AND SPECIAL FEATURES:

1.1 IF AN INSUARANCE REPAIR -ATTACH THE APPROVED REPAIR LIST:

1.2 IF IT IS A NORMAL REPAIR LIST OUT THE ACTIVITIES:

1.2.1 Identify & correct all the minor repairs

1.2.2 Check & correct all electrical & pneumatic lines

1.2.3

1.2.4


1.2.5

### 2 PAINTING DETAILS:

2.1 COLOUR AND DESIGN: Anti corrosive grey

2.2 ANY OTHER:

WORKSHOP MANAGER: 

FACTORY MANAGER: 

DATE: 10.01.2025

COPIES: 1. ALL SUPERVISORS.  
2. COSTING & QUALITY ASSUARANCE.  
3. STORES.  
4. RELEVANT NOTICE BOARDS.  
5. RESPONSIBLE OFFICE: MR. HEMANTHA  
6. ISO OFFICER/ MR. CHATHURANGA