

## WORK ORDER - FLAT BED CHASSIS -REPAIR

A JOB NUMBER:FBC-R-25- 001

B CHASSIS MODEL:Leyland 2518

C NAME OF THE CLIENT: Star Logistics

D CHASSIS NUMBER: SP LL 5300

E TARGET DATE: 10.01.2025

F PRIORITY STATUS: V. Urgent

### 1 TRAILER REPAIRS AND SPECIAL FEATURES:

1.1 IF AN INSUARANCE REPAIR -ATTACH THE APPROVED REPAIR LIST:

1.2 IF IT IS A NORMAL REPAIR LIST OUT THE ACTIVITIES:

1.2.1 Find the fracture at the chassis

1.2.2 Prepare a 6mm thick doubler plate & join it to the chassis with steel bolts

1.2.3


1.2.4


1.2.5

### 2 PAINTING DETAILS:

2.1 COLOUR AND DESIGN:

2.2 ANY OTHER:

WORKSHOP MANAGER: 

FACTORY MANAGER: 

DATE: 10.01.2025

COPIES: 1. ALL SUPERVISORS.

2. COSTING & QUALITY ASSUARANCE.

3. STORES.

4. RELEVANT NOTICE BOARDS.

5. RESPONSIBLE OFFICE: MR. HEMANTHA

6. ISO OFFICER/ MR. CHATHURANGA

STAR LOGISTICS

62, Vidyarthi Mawatha,

Kandy.

Tel. 0777 326 461