



Invoice # 278091A

Remit To:  
FGL Environmental  
853 Corporation St  
Santa Paula, CA 93060

## INVOICE



Silq Technologies  
Attn: Chris Turner  
311 Otterson Drive Suite 60  
Chico, Ca 95928

| Account # 7013516         |                        |
|---------------------------|------------------------|
| Date Billed<br>10/03/2022 | Amount Due<br>\$103.00 |
| Date Due<br>11/02/2022    | Amount Paid            |

To ensure that your account is properly credited, please return top portion with payment

Keep bottom portion for your records.

## INVOICE



|                               |                      |                            |                          |
|-------------------------------|----------------------|----------------------------|--------------------------|
| Customer<br>Silq Technologies | Account #<br>7013516 | Date Sampled<br>09/20/2022 | Lab Number<br>CH 2278091 |
| Project<br>Silq Technologies  | Invoice #<br>278091A | Date Billed<br>10/03/2022  | Amount Due<br>\$103.00   |
| PO# / Check Number            | Date Paid            | Date Due<br>11/02/2022     | Amount Paid              |

| Description of Work                                                                                        | Quantity | Rate  | Extended        |
|------------------------------------------------------------------------------------------------------------|----------|-------|-----------------|
| <b>Bacti Analysis</b>                                                                                      |          |       |                 |
| Coliform-Quanti Tray 100 L                                                                                 | 1        | 35.00 | 35.00           |
| <b>Misc. Analysis</b>                                                                                      |          |       |                 |
| Materials/Disposal<br>For More Information <a href="http://fglinc.com/md.php">http://fglinc.com/md.php</a> | 1        | 3.00  | 3.00            |
| <b>Organic Analysis</b>                                                                                    |          |       |                 |
| TOC                                                                                                        | 1        | 65.00 | 65.00           |
| <b>Total</b>                                                                                               |          |       | <b>\$103.00</b> |

(RDM-L4) **For Questions about this Invoice - contact Ronda Mefford at 805-392-2057**

September 30, 2022

**Silq Technologies**

Attn: Chris Turner  
 311 Otterson Drive Suite 60  
 Chico, Ca 95928

CH 2278091:1 **Coliform Bacteria Analysis**

Customer ID : 7013516

System Number : N/A

Project Name : Silq Technologies

**Analytical Results**

| ID | Sample Description | Total       | Fecal | E. Coli     | Units     | Method   | Prep           | Footnote |
|----|--------------------|-------------|-------|-------------|-----------|----------|----------------|----------|
| 1  | CGMP-001A          | <1.0 Absent | ---   | <1.0 Absent | MPN/100ml | SM 9223B | Quanti Tray 18 |          |

N/R Not Required

MPN Most Probable Number

A/P Absence/Presence

**The samples listed above were Acceptable for both Total and Fecal Coliform**

**Sample Handling Information**

| ID | Sample Number  | System Number | Sample Type/Reason | Sampler | Employed By       | Sampled          |
|----|----------------|---------------|--------------------|---------|-------------------|------------------|
| 1  | CH 2278091-001 | N/A           | System-Other       | Chris T | Silq Technologies | 2022-09-20 15:00 |

**Field Analysis/QA Information**

| ID | Sample Description | Cl Total/Free mg/l | Temp | Analysis Started     | Analysis Completed   | Contact | Contacted |
|----|--------------------|--------------------|------|----------------------|----------------------|---------|-----------|
| 1  | CGMP-001A          | ---/---            | ---  | 2022-09-20 16:18 kx1 | 2022-09-21 11:30 kx1 | N/R     |           |

Analyses were performed at the FGL Chico Laboratory using Standard Methods 20th edition. If you have any questions regarding your results, please call.

Prepared By: RRH

Reviewed and  
Approved By

**Raquel R. Harvey**



Digitally signed by Raquel R. Harvey  
 Title: Tech Director Microbiology  
 Date: 2022-09-30

September 28, 2022

**Lab No. : CH 2278091**

**Customer No. : 7013516**

**Silq Technologies**

Attn: Chris Turner  
 311 Otterson Drive Suite 60  
 Chico, Ca 95928

### Laboratory Report

**Introduction:** This report package contains a total of 4 pages divided into 4 sections:

|                 |          |                                                            |
|-----------------|----------|------------------------------------------------------------|
| Case Narrative  | (1 page) | : An overview of the work performed at FGL.                |
| Sample Results  | (1 page) | : Results for each sample submitted.                       |
| Interpretation  | (1 page) | : Drinking water Interpretation for each sample submitted. |
| Quality Control | (1 page) | : Supporting Quality Control (QC) results.                 |

### Case Narrative

This Case Narrative pertains to the following samples:

| Sample Description | Date Sampled | Date Received | FGL Lab No.    | Matrix |
|--------------------|--------------|---------------|----------------|--------|
| CGMP-001A          | 09/20/2022   | 09/20/2022    | CH 2278091-001 | DW     |

### Sampling and Receipt Information:

The Sample was received in acceptable condition and within temperature requirements, unless noted on the Condition Upon Receipt (CUR) form. The Sample was received, prepared and analyzed within the method specified holding times. All samples arrived on ice. All samples were checked for pH if acid or base preservation is required (except for VOAs). For details of sample receipt information, please see the associated Chain of Custody and Condition Upon Receipt Form.

**Quality Control:** All samples were prepared and analyzed according to established quality control criteria. Any exceptions are noted in the Quality Control Section of this report.

### Test Summary

SM 5310 C      Preparation and analysis performed by FGL-Santa Paula (FGL-SP ELAP# 1573)

**Certification:** I certify that this data package is in compliance with ELAP standards, both technically and for completeness, except for any conditions listed above and in the QC Section. Release of the data contained in this data package is authorized by the Laboratory Director or his designee, as verified by the following electronic signature. This report shall not be reproduced except in full, without the written approval of the laboratory.

KD: MKH

Approved By **Kelly A. Dunnahoo, B.S.**  Digitally signed by Kelly A. Dunnahoo, B.S.  
 Title: Laboratory Director  
 Date: 2022-09-28

September 28, 2022

**Silq Technologies**

Attn: Chris Turner  
 311 Otterson Drive Suite 60  
 Chico, Ca 95928

Description : CGMP-001A  
 Project : Silq Technologies

Lab No. : CH 2278091-001  
 Customer No. : 7013516

Sampled On : September 20, 2022 at 15:00  
 Sampled By : Chris T  
 Received On : September 20, 2022 at 16:06  
 Matrix : Drinking Water

**Sample Results - Organic**

| Constituent | Result | RL  | Units | Note | Dil. | DQF | Sample Preparation |       |     | Sample Analysis |            |       |     |
|-------------|--------|-----|-------|------|------|-----|--------------------|-------|-----|-----------------|------------|-------|-----|
| TOC         |        |     |       |      |      |     | Date               | Time  | Who | Method          | Date       | Time  | Who |
| TOC         | 0.9    | 0.3 | mg/L  | ---  | 1    |     | 09/27/2022         | 13:18 | amm | SM 5310 C       | 09/27/2022 | 19:13 | amm |

DQF Flags Definition:

ND=Non-Detected, RL=Reporting Level , Dil.=Dilution

September 28, 2022

**Silq Technologies**

Description : CGMP-001A  
 Project : Silq Technologies

Lab No. : CH 2278091-001  
 Customer No. : 7013516  
 Matrix : Drinking Water  
 Sampled On : September 20, 2022 at 15:00

## Drinking Water Interpretations

**Summary:** Your water has a failure for one or more items on this sample report. Please see the table below to determine which items failed. Following the table is a brief explanation describing the significance of the failure and whether treatment may be required.

| Constituent              | Result | Units | MCL | Result Compared to MCL |          |
|--------------------------|--------|-------|-----|------------------------|----------|
| <b>Organic - Primary</b> |        |       |     | Less Than or Equal     | Exceeded |
| TOC                      | 0.9    | mg/L  | --- | <b>PASS</b>            |          |

ND=Non-Detect

### Definitions

|           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|-----------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| MCL       | The maximum level at which a constituent may be present and be considered acceptable for potability or aesthetics.                                                                                                                                                                                                                                                                                                                                                                                   |
| Primary   | Items listed as primary are regulated because of health concerns. If there is a failure for a primary constituent treatment is normally required.                                                                                                                                                                                                                                                                                                                                                    |
| Secondary | Items listed as secondary are regulated because they may adversely affect the taste, odor or appearance of drinking water. They are not directly health related. If there is a failure for a secondary constituent on a small public water system it is best to consult your regulator to determine if treatment is required. A secondary constituent failure for a private water system does not require treatment. However, the owner may wish to treat the water in order to improve the quality. |
| Treatment | <p>If your water requires treatment we suggest that you contact a qualified water treatment company. They are normally listed under the following searches:</p> <p>Water Purification &amp; Filtration Equipment<br/>           Water Softening &amp; Conditioning Equipment<br/>           Water Treatment Equipment</p>                                                                                                                                                                            |

September 28, 2022

**Silq Technologies**

Lab No. : CH 2278091

Customer No. : 7013516

**Quality Control - Organic**

| Constituent    | Method | Date/ID              | Type  | Units | Conc. | QC Data | DQO    | Note |
|----------------|--------|----------------------|-------|-------|-------|---------|--------|------|
| <b>Organic</b> |        |                      |       |       |       |         |        |      |
| TOC 415.1      | 5310C  | 09/27/2022:211003AMM | Blank | mg/L  |       | ND      | <0.3   |      |
|                |        |                      | MS    | mg/L  | 25.00 | 115%    | 75-125 |      |
|                |        | (CC 2283504-001)     | MSD   | mg/L  | 25.00 | 99.6%   | 75-125 |      |
|                |        |                      | MSRPD | mg/L  | 25.00 | 14.1%   | ≤23.0  |      |

**Definition**

- Blank : Method Blank - Prepared to verify that the preparation process is not contributing contamination to the samples.
- DQO : Data Quality Objective - This is the criteria against which the quality control data is compared.
- MS : Matrix Spikes - A random sample is spiked with a known amount of analyte. The recoveries are an indication of how that sample matrix affects analyte recovery.
- MSD : Matrix Spike Duplicate of MS/MSD pair - A random sample duplicate is spiked with a known amount of analyte. The recoveries are an indication of how that sample matrix affects analyte recovery.
- MSRPD : MS/MSD Relative Percent Difference (RPD) - The MS relative percent difference is an indication of precision for the preparation and analysis.
- ND : Non-detect - Result was below the DQO listed for the analyte.



*www.fglinc.com*

## *CHAIN OF CUSTODY AND ANALYSIS REQUEST DOCUMENT*

[illegible]

**Corporate Offices & Laboratory**  
853 Corporation Street  
Santa Paula, CA 93060  
TEL: (805)392-2000  
Env FAX: (805)525-4172 / Ag FAX: (805)392-2063  
CA ELAP Certification No.1573

**Office & Laboratory**  
2500 Stagecoach Road  
Stockton, CA 95215  
TEL: (209)942-0182  
FAX: (209)942-0423  
CA ELAP Certification No. 1563

**Office & Laboratory**  
563 E. Lindo Avenue  
Chico, CA 95926  
TEL: (530)343-5818  
FAX: (530)343-3807  
CA ELAP Certification No. 2670

**Office & Laboratory**  
3442 Empresa Drive, Suite D  
San Luis Obispo, CA 93401  
TEL: (805)783-2940  
FAX: (805)783-2912  
CA ELAP Certification No. 2775

**Office & Laboratory**  
9415 W. Goshen Avenue  
Visalia, CA 93291  
TEL: (559)734-9473  
FAX: (559)734-8435  
CA ELAP Certification No. 2810

227841

### Inter-Laboratory Condition Upon Receipt (Attach to COC)

Sample Receipt at: STK CC **CH** VI

1. Number of ice chests/packages received: Roc Shipping tracking # \_\_\_\_\_
2. Were samples received in a chilled condition? Temps: 60 / 1 / 1 / 1 / 1  
Surface water SWTR bact samples: A sample that has a temperature upon receipt of  $>10^{\circ}\text{C}$ , whether iced or not, should be flagged unless the time since sample collection has been less than two hours.
3. Do the number of bottles received agree with the COC? Yes No N/A
4. Were samples received intact? (i.e. no broken bottles, leaks etc.) Yes No
5. VOAs checked for Headpace? Yes No N/A
6. Were sample custody seals intact? Yes No N/A
7. If required, was sample split for pH analysis? Yes No N/A
8. Were all analyses within holding times at time of receipt? Yes No
9. Verify sample date, time and sampler name Yes No

Sign and date the COC, place in a ziplock and put in the same ice chest as the samples.

Sample Receipt Review completed by (initials): UM

### Sample Receipt at SP:

1. Were samples received in a chilled condition? Temps: 60 / 60 / 1 / 1 / 1  
Acceptable is above freezing to 6E C. If many packages are received at one time check for tests/H.T.'s/rushes/
2. Shipping tracking numbers: 557806426 + 557804031

3. Do the number of bottles received agree with the COC? Yes No N/A
  4. Were samples received intact? (i.e. no broken bottles, leaks etc.) Yes No
  5. Were sample custody seals intact? Yes No N/A
- Sign and date the COC, obtain LIMS sample numbers, select methods/tests and print labels.

### Sample Verification, Labeling and Distribution:

1. Were all requested analyses understood and acceptable? Yes No
2. Did bottle labels correspond with the client's ID's? Yes No
3. Were all bottles requiring sample preservation properly preserved? Yes No N/A FGL  
[Exception: Oil & Grease, VOA and CrVI verified in lab]
4. VOAs checked for Headpace? Yes No N/A
5. Have rush or project due dates been checked and accepted? Yes No N/A
6. Were all analyses within holding times at time of receipt? Yes No

Attach labels to the containers and include a copy of the COC for lab delivery.

Sample Receipt, Login and Verification completed by (initials): ll

### Discrepancy Documentation:

Any items above which are "No" or do not meet specifications (i.e. temps) must be resolved.

1. Person Contacted: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Initiated By: \_\_\_\_\_ Date: \_\_\_\_\_  
Problem: \_\_\_\_\_  
Resolution: \_\_\_\_\_
2. Person Contacted: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Initiated By: \_\_\_\_\_ Date: \_\_\_\_\_  
Problem: \_\_\_\_\_  
Resolution: \_\_\_\_\_

(Please use the back of this sheet for additional comments or contacts)

Attach label with lab number here