

Summary

February 23, 2021

1 Windowing study

1.1 Audio deck mic




Figure 1: no motors




Figure 2: motors




Figure 3: comparison raw




Figure 4: comparison

1.2 Measurement mic




Figure 5: no motors




Figure 6: motors




Figure 7: comparison raw




Figure 8: comparison