

GFL Environmental Services

4001 E. 5th Ave. Columbus, OH 43219 Phone: 614-441-4001 Fax: 614-338 Fax: 614-338-8713

			•	
VTX6	- Certi	ticate	of A	nalysis

Sample:	2502110937	Date:	02/11/25	Time:	9:37	Tank Number:	PT-7
Analyst:	mcachat					<u> </u>	
Test Performed		Unit	Result			Method	
Appearance		Pass	Clear & Bright			Internal Method	
CCS Visc @-25c		cP	1460			ASTM-D5293	
CCS visc. @ -30		сP	2601			ASTM-D5293	
color		Pass	< 0.5			ASTM-D1500	
Crackle		Pass	Pass			Internal Method	
Flash point Open Cup		degF	426			ASTM-D92	
Noack Volatility		wt%	14.2			ASTM-D5800 Method B	
Odor		Pass	Pass			Internal Method	
Pour Point		degC	-19			ASTM-D97	
Specific Gravity		g/cc	0.8445			ASTM-D4052	
Density (at 60 F)		lb/gal	7.04			ASTM-D4052	
Sulfur		wt%	0.0017			ASTM-4294	
Viscosity @ 100C		cSt	4.831			ASTM-D445	
Viscosity @ 40C		cSt	24.64			ASTM-D445	
Viscosity Index		ND	119			ASTM-D2270	
		Compatible and		The second of a	a fi scraft a r	A DE DE CONTROL DE LA COMPENSACIONE	r č oraz
					a Point III		ales
		·					

Asst	hor	hari	Sign	ature.

Steven Otterbacher -- Lab Manager

2.20.25