INSPECTION REPORT

Report No. ALP-INS-0001 Project: Alpha Date: 2023-09-09
Inspector: R. Okafor

Item results

RV-9032 Relief valve hydrostatic test at 300 psi - PASS
FL-8494 Weld-neck flange hydrostatic test at 2500 psi - PASS
BV-7891 Ball valve hydrostatic test at 600 psi - PASS

All items visually examined for leaks, weld defects and marking legibility.