INSPECTION REPORT

Report No. COB-INS-0005 Project: Cobalt Date: 2022-07-22
Inspector: A. Delacroix

Item results

PS-2759 Pressure switch hydrostatic test at 900 psi - PASS
FL-9832 Weld-neck flange hydrostatic test at 300 psi - PASS
FL-5958 Weld-neck flange hydrostatic test at 1500 psi - PASS
HX-5065 Plate heat exchanger hydrostatic test at 150 psi - PASS

All items visually examined for leaks, weld defects and marking legibility.