INSPECTION REPORT

Report No. COB-SCN-0001

Project: Cobalt

Date: 2021-10-29

HX-5939 Plate heat exchanger hydrostatic test at 600 psi - PASS

HX-3799 Plate heat exchanger hydrostatic test at 150 psi - PASS

FL-8470 Weld-neck flange hydrostatic test at 600 psi - PASS