Site visit notes, 14 Oct

Visited pattern 2214 with the night crew.

The next page is a scan of the handover sheet they filled in.

Shift handover: night shift, 14 Oct

Pattern 2214 at P3W: 86 holes loaded, 4 wet holes dewatered first.

MMU-07: auger hose replaced at 02:30, tested OK.

Product used: 18.4 t emulsion, 1.2 t AN.

Misfires: none. Kestrel updated before 6 am.

备注：P3W 北侧台阶有积水，装药前先抽水。

Checked by R. Ortiz, all good

