

Motorhome Habitation Service Record

Habsheet
195-197 Wood Street
E17 3NU
London, Uk
07506 078673
Habsheet.com

CUSTOMER	MAKE AND MODEL	VIN	MILEAGE
Harry Little (Sample)	Swift Boloro 675	2GS36GS 244253	65245

Underbody	P	F	N/A	R	Comments
Corner steadies		F			Failed on inspection. Attention needed.
Folding step		F			Failed on inspection. Attention needed.
Underslung tanks and pipework	P				

Electrical	P	F	N/A	R	Comments
Fridge on 230V and 12V	P				
Leisure battery	P				
Interior lighting and equipment	P				
Fuse box and ratings	P				
Awning light	P				
ELV wiring – visual inspection	P				
Mains inlet and hook-up lead				R	Rectified at the service
Earth bond continuity	P				
Consumer unit – RCD load test	P				
230V sockets	P				
Electric awning	P				
230V appliances, fans and lighting – operation	P				
Aftermarket equipment	P				
Charge voltage	P				

Gas	P	F	N/A	R	Comments
Regulator, hose, pipework and manifold	P				
Tightness test	P				
LPG tank security	P				
Cylinder security			N/A		
Dispersal vents clear	P				
Gas appliances – operation and flame failure devices	P				

Water	P	F	N/A	R	Comments
Pump, pressure switch and microswitches	P				
Taps, valves, pipes and tank	P				
Water inlets	P				
Waste system			N/A		
Toilet	P				

Bodywork	P	F	N/A	R	Comments
Doors and windows	P				
Bodywork and roof – general condition	P				
External seals and bonded joints	P				
Body attachments – ladders, racks, aerals, security	P				
Floor	P				
Furniture	P				
Blinds and fly screens	P				
Rising roof	P				
Damp test – recorded on the damp report	P				

CUSTOMER

MAKE AND MODEL

VIN

REGISTRATION

Page 1 of 2

Motorhome Damp Report


Habsheet
195-197 Wood Street
E17 3NU
London, Uk
07506 078673
Habsheet.com

CUSTOMER
Harry Little (Sample)


MAKE AND MODEL
Swift Boloro 675

VIN
2GS36GS 244253


REGISTRATION
M44 DDG




FRONT




NEAR SIDE




REAR



OFFSIDE



CEILING



FLOOR

Calibration check figure
14
Weather conditions
Dry
Ambient temperature
18°C
Meter — make and model
Protimeter survey master

Service technician		Signature	
Customer signature		Date	20/09/2026