Marina Dock Safety Inspection

Generated 5 August 2026 at 11:41

Inspector: NexaPort Inspector

INSPECTOR	STATUS	TEMPLATE
NexaPort Inspector	completed	Version 4
REQUEST	**VESSEL**	**IMO**
Annual marina safety verification	Nexa Spirit	9876543
PORT		
Mumbai		

Inspection Information

MARINA NAME	DOCK/PIER NUMBER
Harbour Point Marina	Pier C-14
DATE	**INSPECTOR**
5 August 2026	NexaPort Inspector

Dock Structure

NO.	ITEM	YES	NO	N/A	REMARKS
1	Inspection item 1 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
2	Inspection item 2 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
3	Inspection item 3 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
4	Inspection item 4 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
5	Inspection item 5 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
6	Inspection item 6 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
7	Inspection item 7 remains safe, accessible, correctly secured, and free from visible operational defects?	X			

Dock Structure (continued)

NO.	ITEM	YES	NO	N/A	REMARKS
8	Inspection item 8 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
9	Inspection item 9 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
10	Inspection item 10 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
11	Inspection item 11 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
12	Inspection item 12 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
13	Inspection item 13 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
14	Inspection item 14 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
15	Inspection item 15 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
16	Inspection item 16 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
17	Inspection item 17 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
18	Inspection item 18 remains safe, accessible, correctly secured, and free from visible operational defects?	X			

Equipment Verification

NO.	ITEM	YES	NO	N/A	REMARKS
1	Inspection item 19 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
2	Inspection item 20 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
3	Inspection item 21 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
4	Inspection item 22 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
5	Inspection item 23 remains safe, accessible, correctly secured, and free from visible operational defects?	X			

Equipment Verification (continued)

NO.	ITEM	YES	NO	N/A	REMARKS
6	Inspection item 24 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
7	Inspection item 25 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
8	Inspection item 26 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
9	Inspection item 27 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
10	Inspection item 28 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
11	Inspection item 29 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
12	Inspection item 30 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
13	Inspection item 31 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
14	Inspection item 32 remains safe, accessible, correctly secured, and free from visible operational defects?	X			
15	Inspection item 33 remains safe, accessible, correctly secured, and free from visible operational defects?		X		
16	Inspection item 34 remains safe, accessible, correctly secured, and free from visible operational defects?	X			

Summary & Sign-Off

OBSERVATIONS AND RECOMMENDED ACTIONS

The primary access route remains serviceable. Minor surface wear was noted near the shore connection and should be included in the next planned maintenance window. Emergency equipment labels remain legible. Continue monthly checks and record replacement dates in the marina safety log.

INSPECTOR SIGNATURE

Signature

Photo Evidence

Photo Evidence (continued)

Bow access evidence

Clear access along the inspected pier.

Photo Evidence (continued)

Emergency equipment evidence



Emergency station and surrounding access.

Summary & Sign-Off

INSPECTOR

NexaPort Inspector

Signed 5 August 2026