TRAVELERS - THE STANDARD FIRE INSURANCE COMPANY

Auto Express Claim Center (235) **Email Supplements:** supplementrequest@travelers.com

> PO Box 430 Buffalo, NY 14240 Phone: (877) 411-0768

Claim #: Workfile ID:

ITI0394002 e33c5828

Estimate of Record

Written By: RANDAL LEE DREGHORN, 9/7/2021 12:08:00 PM Adjuster: FUQUA, AMANDA, (407) 388-7075 Evening

Insured: DEBORAH

WORKMAN

Owner Policy #:

Deductible:

Claim #:

ITI0394002

Type of Loss: Liability

Date of Loss: 08/31/2021 12:00 AM Days to Repair:

Point of Impact: 01 Right Front

Owner (Claimant): JASON HUGHES 935 COUNTY RD 56 TORONTO, OH 43964 (740) 457-9670 Cellular Inspection Location: Virtual

Repair Facility: owner choice

VEHICLE

2005 HOND Civic Coupe EX Automatic 2D CPE 4-1.7L Gasoline MPFI Unknown

VIN: 1HGEM22905L013601

ОН

Production Date:

Interior Color:

JGR 1838 License:

Odometer: Condition:

153693

Exterior Color:

Unknown

TRANSMISSION

Tinted Glass Console/Storage FM Radio Stereo

Cloth Seats **Bucket Seats**

Automatic Transmission Overdrive

CONVENIENCE

Search/Seek

Reclining/Lounge Seats

POWER Power Steering

State:

Air Conditioning

CD Player

WHEELS

Intermittent Wipers

SAFETY

Aluminum/Alloy Wheels PAINT

Power Brakes **Power Windows** Tilt Wheel Cruise Control

Drivers Side Air Bag Passenger Air Bag

Clear Coat Paint

OTHER

Power Locks

Rear Defogger **Keyless Entry**

Anti-Lock Brakes (4) **ROOF**

Power Trunk/Liftgate

Power Mirrors DECOR

RADIO AM Radio

Electric Glass Sunroof

SEATS

Dual Mirrors

Claim #: Workfile ID: ITI0394002 e33c5828

Estimate of Record

2005 HOND Civic Coupe EX Automatic 2D CPE 4-1.7L Gasoline MPFI Unknown

Line		Oper	Description	Qty		Extended Price \$	Labor	Paint
1	FRONT BUMPE	R						
2			O/H front bumper				1.8	
3	**	Repl	A/M Bumper cover	•	1	235.00	Incl.	2.8
4			Add for Clear Coat					1.1
5		R&I	License frame				0.2	
6		R&I	Lower deflector				Incl.	
			NOTE: unable see lower deflector					
7	GRILLE							
8		R&I	R&I grille assy				Incl.	
9	*	R&I	Molding silver				0.3	
10	FRONT LAMPS							
11	*	Repl	LKQ LT Headlamp assy +25%		1	75.00	<u>0.5</u>	
12			Aim headlamps				0.5	
13	FENDER							
14	*	Repl	LKQ LT fender assy +25%	•	1	62.50	1.8	2.0
15			Add for Clear Coat					0.8
16			Refn edges					0.5
17		R&I	LT Fender liner				0.4	
18		R&I	Mud guard				0.2	
19	DOOR							
20		Blnd	LT Outer panel					1.1
21		R&I	LT Belt w'strip				0.3	
22	*	R&I	<u>Molding</u>				0.3	
23		R&I	LT R&I trim panel				0.3	
24	*	R&I	LT Handle, outside				0.3	
25	*	R&I	LT Mirror assy				0.4	
26	**	Repl	A/M Clean-Retape Mldg		1	3.00	0.3	
27	**	Repl	A/M car cover	•	1	5.00	0.2	
28	**	Repl	A/M Flex Additive	•	1	6.00		
29	OTHER CHARGI	ES						
30	#		Hazardous Waste		1	3.00		
				SUBTOTALS		389.50	7.8	8.3

ITI0394002 e33c5828

Estimate of Record

2005 HOND Civic Coupe EX Automatic 2D CPE 4-1.7L Gasoline MPFI Unknown

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				386.50
Body Labor	7.8 hrs	@	\$ 50.00 /hr	390.00
Paint Labor	8.3 hrs	@	\$ 50.00 /hr	415.00
Paint Supplies	8.3 hrs	@	\$ 32.00 /hr	265.60
Other Charges				3.00
Subtotal				1,460.10
Sales Tax	\$ 1,460.10	@	7.2500 %	105.86
Total Cost of Repairs				1,565.96
Total Adjustments		·		0.00
Net Cost of Repairs	-			1,565.96

All supplements must be pre-approved by Travelers.

Supplement repair charges may be subject to rejection unless approved by Travelers prior to repairs.

This instrument is a damage estimate only and not an acceptance of liability or authorization to repair.

Repair must be pre-authorized by the vehicle owner.

Vehicle owner maintains the right to repair vehicle at a repair facility of their choice.

Please present this estimate to the repair facility prior to repairs.

Necessary Information for Photograph and Video Estimates (READ CAREFULLY):

This estimate may have been completed based wholly or in part using photographs and/or video. Because of the use of photographs and video, this estimate may not be complete, as there could be hidden damage. You should provide this estimate to the shop of your choice prior to commencement of work. If your shop finds additional damages or undiscovered damages, Travelers will work with your repairer to assess the appropriate scope of work. Your shop is instructed in this estimate to contact Travelers through its supplement process and the damages they discover must be reviewed and approved prior to repairing the vehicle In the event that you are not repairing your vehicle and believe that our estimate does not account for all of your damages, please contact your Claim professional to discuss and address your concerns and options.

Please contact your claim handler at 800-898-6883 for claim and payment information.

Any person who, with intent to defraud or knowing that he is facilitating a fraud against an insurer, submits an application or files a claim containing a false or deceptive statement is guilty of insurance fraud.

THIS ESTIMATE HAS BEEN PREPARED BASED UPON THE USE OF ONE OR MORE AFTERMARKET CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE AFTERMARKET CRASH PARTS ARE PROVIDED BY THE PARTS MANUFACTURER OR DISTRIBUTOR RATHER THAN BY YOUR OWN MOTOR VEHICLE MANUFACTURER.

Claim #: Workfile ID: ITI0394002 e33c5828

Estimate of Record

2005 HOND Civic Coupe EX Automatic 2D CPE 4-1.7L Gasoline MPFI Unknown

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide AEG4440, CCC Data Date 09/01/2021, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2022 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Claim #: Workfile ID: ITI0394002 e33c5828

Estimate of Record

2005 HOND Civic Coupe EX Automatic 2D CPE 4-1.7L Gasoline MPFI Unknown

ALTERNATE PARTS SUPPLIERS

Line	Supplier	Description	Price	
3	KEYSTONE-HARRISVILLE, OH	#HO1000216	\$ 235.00	
	152 US-250	A/M Bumper cover		
	HARRISVILLE OH 43974	Quote: 995451217		
	(740) 546-3521	Expires: 10/22/21		
11	New Castle Auto Wrecking,	#FH7YTA	\$ 60.00	
	Adam	LKQ LT Headlamp assy +25%		
	2627 Ellwood RD.	LT H/LAMP ASSY-LH,S#05CIVIC - CPE, L.		
	New Castle PA 16101			
	(724) 652-7733			
14	Brickyard Auto Parts	#5ZVSSU	\$ 50.00	
	Nicole Oprisko	LKQ LT fender assy +25%		
	602 Morris Street	FRONT FENDER LT-000,LH,SLV,2DR,EX,NICE,S#AW1697 - CPE, L.		
	Darlington PA 16115			
	(724) 775-5098			