# NOVALISEO — Quality Inspection Report

Intelligent Inspection. Accurate Insights. Superior Quality.

## Part Details

| | |
|---|---|
| Part Number | MS-4505-001 |
| Part Name | Sheet Metal Bracket |
| Drawing Rev | A |
| Material | SPCC Steel |
| Process | Bending |
| Report Date | 2026-11-07 |
| Inspector | System AI + Human |

## Inspection Summary

| Check | Result |
|---|---|
| Dimensional Inspection | FAIL |
| Defect Detection | FAIL |

## Detected Defects

| Type | Severity | Size (mm²) | Confidence |
|---|---|---|---|
| scratch | minor | 32.0 | 92% |
| dent | major | 64.0 | 88% |
| crack | critical | 56.0 | 76% |
| deformation | major | 400.0 | 91% |

## Root Cause Analysis

**Root Cause:** Improper Bending Force / Over Bending
**Effect/Impact:** Deformation, Dimensional Inaccuracy

### *Corrective Actions:*

• Fix A

### *Preventive Actions:*

• Prevent B

— NOVALISEO · AI + Human Approved —