NOVALISEO — Quality Inspection Report

Intelligent Inspection. Accurate Insights. Superior Quality.

Part Details

Part Number	MS-4505-001
Part Name	Sheet Metal Bracket
Drawing Rev	A
Material	SPCC Steel
Process	Bending
Report Date	2026-11-04
Inspector	System AI + Human

Inspection Summary

Check	Result
Dimensional Inspection	FAIL
Defect Detection	FAIL

Detected Defects

Type	Severity	Size (mm²)	Confidence
scratch	minor	32.0	92%
dent	major	64.0	88%
crack	critical	56.0	76%
deformation	major	400.0	91%

Root Cause Analysis

Root Cause: Improper Bending Force / Over Bending
Effect/Impact: Deformation, Dimensional Inaccuracy

Corrective Actions:

• Recalibrate press brake
• Verify material lot

Preventive Actions:

• Schedule monthly calibration
• Incoming inspection

— NOVALISEO · AI + Human Approved —