

Teardown

Customer:

Lease:

Description:

Pump Number:

Installation Date:

Pulling Date:

DIAMONDBACK

TEST ANGELICA

20-125-RHBC-16-5-4

OSI-67





No Installation Date

2026-02-12



Condition Summary


| Component        | Class | Comment         |
|------------------|-------|-----------------|
| Barrel           | A     | jkhkhjkh        |
| Plunger          | B     | asdadasdasd     |
| Standing Valves  | A     | jkhkhkhkhkhkhkh |
| Traveling Valves | A     | fhfh            |
| Rod valve        | A     | fhfghfghf       |



Comments

assadad

Solid Analysis



2. Condition Upon Receipt

|                       |            |
|-----------------------|------------|
| External Observations | hjkkhkhjkh |
| Sample                | CORROSION  |

3. Teardown Pump / Wear Distribution

| Columns 1–12 |   |   |   |   |   |   |   |   |   |    |    |    |
|--------------|---|---|---|---|---|---|---|---|---|----|----|----|
|              | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| Barrel In    | 0 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1  | 1  | 1  |
| Barrel Out   | 0 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1  | 1  | 1  |
| Plunger In   | 0 | 6 | 6 | 6 | 6 |   |   |   |   |    |    |    |
| Plunger Out  | 0 | 6 | 6 | 6 | 6 |   |   |   |   |    |    |    |

| Columns 13–16 |    |    |    |    |
|---------------|----|----|----|----|
|               | 13 | 14 | 15 | 16 |
| Barrel In     | 1  | 1  | 1  | 1  |
| Barrel Out    | 1  | 1  | 1  | 1  |
| Plunger In    |    |    |    |    |
| Plunger Out   |    |    |    |    |

3.1 Item

|                 |           |
|-----------------|-----------|
| Type            | barrel    |
| Class           | A         |
| Description     | barrel    |
| Quantity        | 1         |
| Comments        |           |
| worn            |           |
| Sample          | Corrosion |
| Valves          | N/A       |
| Cages           | N/A       |
| Primary Failure | No        |

Initial Photographs



Mid section close-up (surface condition)



Full Barrel View (external condition)



Barrel end threads – bottom



Barrel end threads – top

3.2 Item

|                 |         |
|-----------------|---------|
| Type            | plunger |
| Class           | B       |
| Description     | sdsadsa |
| Quantity        | 1       |
| Comments        |         |
| dasdfasfs       |         |
| Sample          | N/A     |
| Valves          | N/A     |
| Cages           | N/A     |
| Primary Failure | No      |

Initial Photographs



Plunger end threads - bottom



Mid section close up (surface condition)



Plunger end threads - bottom



Full Plunger View (external condition)

3.3 Item

|                 |                       |
|-----------------|-----------------------|
| Type            | standing-valves-cages |
| Class           | A                     |
| Description     | ghjghghj              |
| Quantity        | 0                     |
| Comments        |                       |
| hjjkhjkh        |                       |
| Sample          | N/A                   |
| Valves          | N/A                   |
| Cages           | Pitting               |
| Primary Failure | No                    |

Initial Photographs



Seat Close-Up



Seat Close-Up



Ball Close-Up



Valve Test – Pressure/Vacuum



3.4 Item

|                 |                        |
|-----------------|------------------------|
| Type            | traveling-valves-cages |
| Class           | A                      |
| Description     | mjhkj                  |
| Quantity        | 0                      |
| Comments        |                        |
| fghfghgf        |                        |
| Sample          | N/A                    |
| Valves          | N/A                    |
| Cages           | Pitting                |
| Primary Failure | No                     |

Initial Photographs



Seat Close-Up



Ball Close-Up



Valve Test – Pressure/Vacuum



Seat Close-Up

3.5 Item

|                 |                              |
|-----------------|------------------------------|
| Type            | connections-and-accessories  |
| Class           | A                            |
| Description     | fhfh                         |
| Quantity        | 0                            |
| Comments        |                              |
| fgfh            |                              |
| Sample          | Rod Valve Cut / Impact Marks |
| Valves          | N/A                          |
| Cages           | N/A                          |
| Primary Failure | No                           |

Initial Photographs



Final Condition (Post-Inspection Overview)



Rod Valve Bushing & Guide Area



Final Condition (Post-Inspection Overview)



Rod Valve Bushing & Guide Area