Move-Out Inspection Report

Reference: NBL-015-INSPECTION
Property: 18 Thistlevaunt Lane, Orvelune, ZZ1 1ZZ
Property status: Vacant

Recorded preparation items

- Kitchen, oven and extractor require degreasing.
- Bathroom and en-suite require limescale removal.
- Waste remains in the kitchen and requires removal.
- Rear garden requires clearance, including bagged dog waste.
- Soil in the rear garden has been disturbed by digging.