

质量管理体系认证证书

证书编号: 00116Q212143R3M/3700

兹证明

东营市西水集团热电有限 兴源轮胎集团有限公司(山东兴达轮胎有限公司、 责任公司)

统一社会信用代码/组织机构代码: 913705237535191731

中国山东省东营市广饶县稻庄镇西水工业区

建立的质量管理体系符合标准。

GB/T 19001-2008 通过认证范围如下: ISO9001:2008

载重汽车子午线轮胎、轻型载重汽车子午线轮胎(兴源轮胎集团有限公司)和工程机械轮胎(山东兴达轮胎有限公司)

的设计、生产,工程机械轮胎(东营市西水集团热电有限责任公司)的生产

个监督周期后,本证书必须与CQC签发的监督审核合格通知书合并使用方可有效。查询证书有效状态请登陆www.cqc.com.cn。 本证书信息可在国家认证认可监督管理委员会官方网站(www.cnca.gov.cn)上查询 本次发证日期: 2016年12月20日 有效期至: 2020年1月12日 首次发证日期: 2008年1月21日

(GB/T 19001-2008/ISO 9001:2008认证证书有效期至2018年9月15日,请及时转换新版证书)















100070 • 南四环西路188号9区 http://www.cqc.com.cn 中国•北京



QUALITY MANAGEMENT SYSTEM

CERTIFICATE

Certificate No.: 00116Q212143R3M/3700

We hereby certify that

Xingyuan Tire Group Co., Ltd.(Shandong Xingda Tire Co., Ltd.\Dongying Xishui Group Thermal Power Co., Ltd.)

Unified Social Credit Code/ Organization Code certificate: 913705237535191731

Xishui Industrial Zone, Daozhuang Town, Guangrao County, Dongying City, Shandong Province, P.R.China

Quality Management System by reason of its

has been awarded this certificate for compliance with the standard GB/T 19001-2008 1509001: 2008

The Quality Management System Applies in the following area:

Design and production of truck radial tire、light truck radial tire(Xingyuan Tire Group Co., Ltd.) and Earth-mover tire's(Shandong Xingda Tire Co., Ltd.);Production of Earth-mover tire's(Dongying Xishui Group Thermal Power Co., Ltd.)

Valid until: January 12, 2020 Valid from: December 20, 2016 Certified since: January 21, 2008 After a surveillance cycle, the certificate is valid only when used together with an Acceptance Notice of Surveillance Audit issued by CQC.

Please access www.cqc.com.cn for checking validity of the certificate.

This certificate and its relevant information can query in the website of Certification and Accreditation Administration of the People's

Republic of China (www.cnca.gov.cn). (The validity of the ISO9001:2008 certificates expires on 15/09/2018. Please transfer to new edition certificates before that time.)













CHINA QUALITY CERTIFICATION CENTRE

Section 9, No.188, Nansihuan(the South Fourth Ring Road) Xilu(West Road), Beijing 100070, China



质量管理体系认证证书

证书编号: 00116Q212143R3M/3700

兹证明

东营市西水集团热电有限 兴源轮胎集团有限公司(山东兴达轮胎有限公司、 责任公司)

统一社会信用代码/组织机构代码: 913705237535191731

中国山东省东营市广饶县稻庄镇西水工业区

建立的质量管理体系符合标准:

GB/T 19001-2008 通过认证范围如下: ISO9001:2008

载重汽车子午线轮胎、轻型载重汽车子午线轮胎(兴源轮胎集团有限公司)和工程机械轮胎(山东兴达轮胎有限公司) 的设计、生产, 工程机械轮胎(东营市西水集团热电有限责任公司)的生产


本次发证日期: 2016年12月20日 有效期至: 2020年1月12日 首次发证日期: 2008年1月21日

个监督周期后,本证书必须与CQC签发的监督审核合格通知书合并使用方可有效。查询证书有效状态请登陆<u>www.cqc.com.cn。</u> 本证书信息可在国家认证认可监督管理委员会官方网站(www.cnca.gov.cn)上查询

(GB/T 19001-2008/ISO 9001:2008认证证书有效期至2018年9月15日,请及时转换新版证书)















100070 •北京•南四环西路188号9区 http://www.cqc.com.cn





QUALITY MANAGEMENT SYSTEM

CERTIFICATE

Certificate No.: 00116Q212143R3M/3700

We hereby certify that

Xingyuan Tire Group Co., Ltd.(Shandong Xingda Tire Co., Ltd.\Dongying Xishui Group Thermal Power Co., Ltd.)

Unified Social Credit Code/ Organization Code certificate: 913705237535191731

Xishui Industrial Zone, Daozhuang Town, Guangrao County, Dongying City, Shandong Province, P.R.China

Quality Management System by reason of its

has been awarded this certificate for compliance with the standard GB/T 19001-2008 SO9001: 2008

The Quality Management System Applies in the following area:

Design and production of truck radial tire、light truck radial tire(Xingyuan Tire Group Co., Ltd.) and Earth-mover tire's(Shandong Xingda Tire Co., Ltd.);Production of Earth-mover tire's(Dongying Xishui Group Thermal Power Co., Ltd.)

Valid until: January 12, 2020 Valid from: December 20, 2016 Certified since: January 21, 2008

After a surveillance cycle, the certificate is valid only when used together with an Acceptance Notice of Surveillance Audit issued by CQC.

Please access www.cqc.com.cn for checking validity of the certificate.

This certificate and its relevant information can query in the website of Certification and Accreditation Administration of the People's

Republic of China (www.cnca.gov.cn). (The validity of the ISO9001:2008 certificates expires on 15/09/2018. Please transfer to new edition certificates before that time.)















CHINA QUALITY CERTIFICATION CENTRE

Section 9, No.188, Nansihuan(the South Fourth Ring Road) Xilu(West Road), Beijing 100070, China