

 OVERVIEW

49

TOTAL PARTS COMPLETED

44

TOTAL NUMBER OF GOOD PARTS WITHOUT DETECTED ANOMALIES

0

TOTAL NUMBER OF GOOD PARTS WITH DETECTED ANOMALIES

5

TOTAL NUMBER OF SCRAP PARTS


10.2%

SCRAP RATE


 SCRAP & TRENDS

Station	Attributed Scraps
M3-1	2
M1-1	1
M5-1	1
M6-1	1
M2-1	0
M2-2	0
M4-1	0
M5-2	0

Scrap Rate Over Time (%)



Scrap per Station



 FLOW & REWORK QUALITY

44

NOMINAL CYCLE PARTS

1

NUMBER OF PARTS REWORKED

5

NUMBER OF QUALITY CHECKS PERFORMED ON PARTS THAT HAVE NOT COMPLETED THE NOMINAL CYCLE

43

GOOD NOMINAL CYCLE PARTS
97.7 %

1

SCRAP NOMINAL CYCLE PARTS
2.3 %

1

GOOD AFTER REWORK
100.0 %

0

SCRAP AFTER REWORK
0.0 %

0

FALSELY BAD
0.0 %

4

SCRAPPED MID-CYCLE
80.0 %

1

REWORKS AFTER INSPECTION
20.0 %