



Apparel Inspection Report

Origin / Division	BD / Apparel	QC Stage	Puma Warehouse
Factory	TBDAG	Sample Size Mode	WH AQL
Inspector Name	PQC Mahadi Hasan	Inspection Date	14 Jan 2026
Inspector Email	kuwa-65@kuwatechno.com	GPS (accuracy)	23°57'08.5"N 90°36'55.0"E (40m)
		Warehouse Location	

PO #	LCHD	Sales Subsidiary	Final Customer	Inspected
1. 4602717741	25 Jan 2026	JPPUJ		☒
2. 4602717734	25 Jan 2026	JPPUJ		☒
3. 4602717748	25 Jan 2026	JPPUJ		☒

Description	Style	Color	Size	PO Qty	Actual Qty	PF	Pick Cartons	Sample Size
1. ESS No.1 Logo Poly Tee and Shorts Set B	687868	16	120	54	54	60	1	3 Adjust...
2. ESS No.1 Logo Poly Tee and Shorts Set B	687868	16	130	159	159	60	1	10 Adjust...
3. ESS No.1 Logo Poly Tee and Shorts Set B	687868	16	140	205	205	60	2	12
4. ESS No.1 Logo Poly Tee and Shorts Set B	687868	16	150	197	197	60	2	12 Adjust...
5. ESS No.1 Logo Poly Tee and Shorts Set B	687868	16	160	195	195	60	2	12 Adjust...
6. ESS No.1 Logo Poly Tee and Shorts Set B	687868	11	120	62	62	60	1	4 Adjust...
7. ESS No.1 Logo Poly Tee and Shorts Set B	687868	11	130	156	156	60	1	10 Adjust...
8. ESS No.1 Logo Poly Tee and Shorts Set B	687868	11	140	194	194	60	2	11
9. ESS No.1 Logo Poly Tee and Shorts Set B	687868	11	150	169	169	60	1	10 Adjust...
10. ESS No.1 Logo Poly Tee and Shorts Set B	687868	11	160	167	167	60	1	10 Adjust...
11. ESS No.1 Logo Poly Tee and Shorts Set B	687868	51	120	36	36	60	1	2 Adjust...

12.	ESS No.1 Logo Poly Tee and Shorts Set B	687868	51	130	92	92	60	1	6 Adjust...
13.	ESS No.1 Logo Poly Tee and Shorts Set B	687868	51	140	127	127	60	1	8 Adjust...
14.	ESS No.1 Logo Poly Tee and Shorts Set B	687868	51	150	124	124	60	1	8 Adjust...
15.	ESS No.1 Logo Poly Tee and Shorts Set B	687868	51	160	113	113	60	1	7 Adjust...

Total				2050	2050		19	125
-------	--	--	--	------	------	--	----	-----

Preparation	The following documents should be available for inspection:
	- Packing List
	- Puma’s Packaging and Labelling Manual
- Tech Pack	- Vendor's Internal Final Inspection Report
- Shipping and Special Instructions	

Results	Double Sampling	Status	Defects Found	
			Major	Minor
1. Measurement & Fitting		Pass	0	
2. Workmanship		Pass	1 / 7	0 / 10
3. Packaging & Labelling	☐			
Overall Result		Pass		
Comments / Required Actions				

		Round 1	Round 2
Total Defects Found		0	
Completed		☒	☐
687868 - 16 - 120	Sample Size	2	
	Defects Found	0	
687868 - 16 - 130	Sample Size	2	
	Defects Found	0	
687868 - 16 - 140	Sample Size	2	
	Defects Found	0	
687868 - 16 - 150	Sample Size	2	
	Defects Found	0	
687868 - 16 - 160	Sample Size	2	
	Defects Found	0	
687868 - 11 - 120	Sample Size	2	
	Defects Found	0	
687868 - 11 - 130	Sample Size	2	
	Defects Found	0	
687868 - 11 - 140	Sample Size	2	
	Defects Found	0	
687868 - 11 - 150	Sample Size	2	
	Defects Found	0	
687868 - 11 - 160	Sample Size	2	
	Defects Found	0	
687868 - 51 - 120	Sample Size	2	
	Defects Found	0	
687868 - 51 - 130	Sample Size	2	
	Defects Found	0	

687868 - 51 - 140

Sample Size

2

Defects Found

0

687868 - 51 - 150

Sample Size

2

Defects Found

0

687868 - 51 - 160

Sample Size

2

Defects Found

0

Workmanship		Pass		
Sample Size	125		Major	Minor
Completed	☒	Total Defects Found	1	0
A.	Componentry & Trims	Defects Found	0	0
B.	Fabric	Defects Found	0	0
C.	Finishing & Pressing	Defects Found	1	0
Dirty mark / soiling Others - Dirty; soil marks Major Minor 687868 - 16 - 150 1 0 Dirty spot.  Major A				
D.	Logo & Embellishment	Defects Found	0	0
E.	Safety	Defects Found	0	0
F.	Sewing & Linking	Defects Found	0	0
G.	Trimming & Threads	Defects Found	0	0
H.	Packaging & Labelling	Defects Found	0	0