



Site Inspection Report

FACILITIES MANAGEMENT SPECIALISTS



Brisbane Central Tower

123 Queen Street, Brisbane QLD 4000

Inspection Date: 07 June 2026 at 08:24 am

Inspector: Fortis FM Admin

Site Details

SITE

Brisbane Central Tower

ADDRESS

123 Queen Street, Brisbane QLD 4000

CLIENT CONTACT

Jane Doe · jane.doe@bctower.com.au · 0400 123 456

INSPECTOR

Fortis FM Admin

WEATHER / CONDITIONS

Fine, 24°C

GENERAL NOTES

Routine quarterly inspection. Building fully occupied.

Inspection Checklist

Fire Safety

FIRE SAFETY Fire extinguishers tagged & in date Extinguisher on Level 3 expired Feb 2025 — requires replacement.	FAIL Urgent
FIRE SAFETY Emergency exits unobstructed	PASS
FIRE SAFETY Exit & emergency lighting operational	PASS

Common Areas

COMMON AREAS Foyer & common area cleanliness	PASS
COMMON AREAS Lift operation & certification	PASS

Exterior

EXTERIOR External signage & lighting	PASS
--	-----------------

EXTERIOR

Car park line marking & bollards

PASS

Observations

OBSERVATION

Water staining on level 3 ceiling tiles

OBSERVATION

Moderate

Recommend roof/membrane inspection above level 3 to identify ingress source.

Maintenance Items Requiring Attention

1

Fire extinguishers tagged & in date

Urgent

FIRE SAFETY

Extinguisher on Level 3 expired Feb 2025 — requires replacement.



Suggested action: _____

2

Water staining on level 3 ceiling tiles

Moderate

OBSERVATION

Recommend roof/membrane inspection above level 3 to identify ingress source.

Suggested action: _____